

INSPECTION SHEET 検品書
CRAWLER CRANE クローラクレーン

INSPECTION DATE	2026/3/26	MAKE	HITACHI	MODEL	KH180-3
SERIAL No.	PLATE : 242-1649	STAMP		242-1649	
HR METER	UNKNOWN	HR	SHOE	760FLAT	YEAR YR

ENGINE : MODEL		S/N
Oil leakage	<input checked="" type="radio"/> FAIR · Attn	
Blow-By	<input checked="" type="radio"/> FAIR · Attn	A LITTLE · MIDDLE · SEVERE
Sound	<input checked="" type="radio"/> FAIR · Attn	
Oil	<input checked="" type="radio"/> FAIR · Attn	
Exhaust Color	<input checked="" type="radio"/> FAIR · Attn	
OPERATION PUMP		
Sound	<input checked="" type="radio"/> FAIR · Attn	
Oil leakage	<input checked="" type="radio"/> FAIR · Attn	
Power	<input checked="" type="radio"/> FAIR · Attn	
COOLING SYSTEM		
Radiator	<input checked="" type="radio"/> FAIR · Attn	
Oil Cooler	<input checked="" type="radio"/> FAIR · Attn	
OPERATING SYSTEM		
Computer	<input checked="" type="radio"/> OK · NG	
Swing	<input checked="" type="radio"/> FAIR · Attn	
Travel	<input checked="" type="radio"/> FAIR · Attn	
BOOM		
MAIN BOOM	TOP, BOTTOM, 6m × 2, 3m × 2	
BOOM TOTAL	31m	
TOP SHEAVE	<input checked="" type="radio"/> YES · NO	
JIB		
TOWER		

INTERIOR		See Photos. 写真参照
INTERIOR COND.	CLEAN · FAIR	<input checked="" type="radio"/> DIRTY
Operator's Seat	<input checked="" type="radio"/> FAIR · Attn	
Glasses	<input checked="" type="radio"/> FAIR · Attn	
AirCon	A/C · H/C · <input checked="" type="radio"/> H only · C only · None	
UNDERCARRIAGE : See Photos. 写真参照		
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		3
COMMENT		
左右キヤタたるみあり TRACK LINKS: WORN		
WEIGHT	2	
HOOK	50t, 30t, BALL	
FREE FALL	<input checked="" type="radio"/> YES · NO	
LIFTER	YES · <input checked="" type="radio"/> NO	
COMMENT		
E/Gストップ不良 ENGINE STOPPER: MALFUNCTION		
補巻ワイヤー欠 AUXILIARY HOISTING WIRE: MISSING		
@NARITA YARD		
BOOM: TOP, BOTTOM, 6m × 1		
WEIGHT × 2, 50t HOOK		
@YOTSUKAIDO YARD		
BOOM: 6m × 1, 3m × 2		
HOOK: 30t, BALL		
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		1

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。