

INSPECTION SHEET 検品書
CRAWLER CRANE クローラクレーン

INSPECTION DATE	2026/3/26	MAKE	SUMITOMO	MODEL	SCX900-2C3
SERIAL No.	PLATE : SC090-7188	STAMP		SC090-7188	
HR METER	26603	HR	SHOE	830FLAT	YEAR YR

ENGINE : MODEL		S/N
Oil leakage	<input checked="" type="radio"/> FAIR · Attn	
Blow-By	<input checked="" type="radio"/> FAIR · Attn	A LITTLE · MIDDLE · SEVERE
Sound	<input checked="" type="radio"/> FAIR · Attn	
Oil	<input checked="" type="radio"/> FAIR · Attn	
Exhaust Color	<input checked="" type="radio"/> FAIR · Attn	
OPERATION PUMP		
Sound	<input checked="" type="radio"/> FAIR · Attn	
Oil leakage	<input checked="" type="radio"/> FAIR · Attn	
Power	<input checked="" type="radio"/> FAIR · Attn	
COOLING SYSTEM		
Radiator	<input checked="" type="radio"/> FAIR · Attn	
Oil Cooler	<input checked="" type="radio"/> FAIR · Attn	
OPERATING SYSTEM		
Computer	<input checked="" type="radio"/> OK · NG	
Swing	<input checked="" type="radio"/> FAIR · Attn	
Travel	<input checked="" type="radio"/> FAIR · Attn	
BOOM		
MAIN BOOM	TOP, BOTTOM, 9m × 3, 6m × 1, 3m × 1	
BOOM TOTAL	48m	
TOP SHEAVE	<input checked="" type="radio"/> YES · NO	シーブ2車 2-SHEAVE TOP BLOCK
JIB		
TOWER		

INTERIOR		See Photos. 写真参照
INTERIOR COND.	CLEAN · <input checked="" type="radio"/> FAIR · DIRTY	
Operator's Seat	<input checked="" type="radio"/> FAIR · Attn	
Glasses	<input checked="" type="radio"/> FAIR · Attn	
AirCon	<input checked="" type="radio"/> A/C · H/C · H only · C only · None	
UNDERCARRIAGE : See Photos. 写真参照		
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		4
COMMENT		
WEIGHT	3	
HOOK	50t, 30t, LIGHT HOOK	
FREE FALL	<input checked="" type="radio"/> YES · NO	
LIFTER	<input checked="" type="radio"/> YES · NO	
COMMENT		
第3ドラム付 W/3rd DRUM		
@NARITA YARD		
BOOM: TOP, BOTTOM, 9m × 1		
WEIGHT × 3, 50t HOOK		
@SAKURA YARD		
BOOM: 9m × 2, 6m × 1, 3m × 1		
HOOK: 30t, LIGHT HOOK		
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		4

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。