

INSPECTION SHEET 検品書
CRAWLER CRANE クローラクレーン

INSPECTION DATE	2026/3/27	MAKE	SUMITOMO	MODEL	SC650-2	
SERIAL No.	PLATE : SC065-1092	STAMP	SC065-1092			
HR METER	3708	HR	SHOE	800FLAT	YEAR	YR

ENGINE : MODEL		S/N		TA33827
Oil leakage	FAIR · Attn	*1		
Blow-By	FAIR · Attn	A LITTLE · MIDDLE · SEVERE		
Sound	FAIR · Attn			
Oil	FAIR · Attn			
Exhaust Color	FAIR · Attn			
OPERATION PUMP				
Sound	FAIR · Attn			
Oil leakage	FAIR · Attn			
Power	FAIR · Attn			
COOLING SYSTEM				
Radiator	FAIR · Attn			
Oil Cooler	FAIR · Attn			
OPERATING SYSTEM				
Computer	OK · NG			
Swing	FAIR · Attn			
Travel	FAIR · Attn			
BOOM				
MAIN BOOM	TOP, BOTTOM, 6m × 4, 3m × 1			
BOOM TOTAL	37m			
TOP SHEAVE	YES · NO			
JIB				
TOWER				

INTERIOR		See Photos. 写真参照	
INTERIOR COND.	CLEAN · FAIR · DIRTY		
Operator's Seat	FAIR · Attn		
Glasses	FAIR · Attn		
AirCon	A/C · H/C · H only · C only · None		
UNDERCARRIAGE : See Photos. 写真参照			
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			4
COMMENT			
左右キャタタるみあり TRACK LINKS: WORN			
WEIGHT	3		
HOOK	65t, 35t, BALL		
FREE FALL	YES · NO		
LIFTER	YES · NO		
COMMENT			
*1 オイルパン合わせにじみあり			
*1 CONNECTING PART BETWEEN OIL PAN & ENGINE BLOCK: OIL Oozing			
@NARITA YARD			
BOOM: TOP, BOTTOM, 6m × 1			
65t HOOK			
@SAKURA YARD			
BOOM: 6m × 3, 3m × 1			
HOOK: 35t, BALL			
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。