

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2026/3/17	MAKE	KOMATSU	MODEL	PC138US-8S
SERIAL	25048		STAMP	KMTPC236JGA025048	
HR METER	7227	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	600G	

ENGINE : MODEL 4D95LE-5 S/N 562013	
Oil leakage	FAIR · Attn
Blow-By	FAIR · Attn A LITTLE · MIDDLE · SEVERE
Sound	FAIR · Attn
Oil	FAIR · Attn
Exhaust Color	FAIR · Attn
US EPA	YES · NO
MAIN PUMP	
Sound	FAIR · Attn
Oil leakage	FAIR · Attn ホースにじみあり SOME HOSES: OIL OOZING
Power	FAIR · Attn
COOLING SYSTEM	
Radiator	FAIR · Attn
Oil Cooler	FAIR · Attn
OPERATING SYSTEM	
Swing	FAIR · Attn ガタあり SWING: LOOSE
Travel	FAIR · Attn
INTERIOR See Photos. 写真参照	
INTERIOR COND.	CLEAN · FAIR · DIRTY
Operator's Seat	FAIR · Attn
Glasses	FAIR · Attn
AirCon	A/C · H/C · H only · C only · None
BOOM / ARM / BKT	
Boom	FAIR · Attn
Boom Cylinder	FAIR · Attn 左側にじみあり LEFT CYLINDER: OIL OOZING
Arm	FAIR · Attn ガタあり LOOSE
Arm Cylinder	FAIR · Attn
ATTACHMENT	FAIR · Attn
BKT Cylinder	FAIR · Attn

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
COMMENT	
BKT	STD / SLOPE / NARROW / SKELETON / OTHER ()
Lever	LONG · WRIST
Multi	MULTI · 2 · NO
ARM-CRANE	YES · NO
BLADE	YES · NO
OFFSET	YES · NO
OFFSET Cylinder	FAIR · Attn
Piping	YES · NO Breaker only · Multi *1
COMMENT	
ROPSプレート欠 ROPS PLATE: MISSING	
ウインチ付 W/WINCH MAKE: NANSEI PW-02-A-710492	
ウインチ: 油圧の掛かる音はするが動作しない	
WINCH: NOT WORKING (JUST HYDRAULIC ENGAGEMENT NOISES)	
オイルフィルターホース油漏れあり OIL FILTER HOSES: OIL LEAKING	
*1 油圧起きない(ペダル欠、レバーS/W付)	
*1 UNABLE TO SUPPLY ANY HYDRAULIC PRESSURE	
(NO PEDAL, W/OPERATION LEVER SWITCHES)	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。