

**INSPECTION SHEET 検品書**  
**EXCAVATOR バックホー**

INSPECTION DATE	2026/3/25	MAKE	HITACHI	MODEL	EX75UR
SERIAL	10L-7142		STAMP	10L-7142	
HR METER	1992	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	450G	

<b>ENGINE : MODEL</b>		<b>S/N</b>
Oil leakage	FAIR · Attn	
Blow-By	FAIR · Attn	A LITTLE · MIDDLE · SEVERE
Sound	FAIR · Attn	
Oil	FAIR · Attn	
Exhaust Color	FAIR · Attn	
US EPA	YES · NO	
<b>MAIN PUMP</b>		
Sound	FAIR · Attn	
Oil leakage	FAIR · Attn	にじみあり OIL OOZING
Power	FAIR · Attn	*1
<b>COOLING SYSTEM</b>		
Radiator	FAIR · Attn	
Oil Cooler	FAIR · Attn	
<b>OPERATING SYSTEM</b>		
Swing	FAIR · Attn	ガタ大 SWING: MUCH LOOSE
Travel	FAIR · Attn	
<b>INTERIOR See Photos. 写真参照</b>		
INTERIOR COND.	CLEAN · FAIR · DIRTY	
Operator's Seat	FAIR · Attn	破れあり HUGE CUTS
Glasses	FAIR · Attn	天窗ひび割れあり SKYLIGHT: CRACKED
AirCon	A/C · H/C · H only · C only · None	
<b>BOOM / ARM / BKT</b>		
Boom	FAIR · Attn	
Boom Cylinder	FAIR · Attn	油漏れあり OIL LEAKING
Arm	FAIR · Attn	ガタあり LOOSE
Arm Cylinder	FAIR · Attn	油漏れ小 OIL LEAKING
ATTACHMENT	FAIR · Attn	ガタあり LOOSE
BKT Cylinder	FAIR · Attn	油漏れあり OIL LEAKING

<b>UNDERCARRIAGE : See Photos. 写真参照</b>	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2
<b>COMMENT</b>	
上部旋回体下周り油漏れ小 BOTTOM OF BODY: OIL LEAKING	
操作レバー左右下周り油漏れ小	
BOTTOMS OF OPERATION LEVERS: OIL LEAKING	
BKT	STD / SLOPE / NARROW / SKELETON / OTHER ( )
Lever	LONG · WRIST
Multi	MULTI · 2 · NO
ARM-CRANE	YES · NO *2
BLADE	YES · NO
OFFSET	YES · NO 補修跡あり REPAIRED
OFFSET Cylinder	FAIR · Attn 油漏れ小 OIL LEAKING
Piping	YES · NO Breaker only · Multi
<b>COMMENT</b>	
E/G掛けて1分くらいでブーム上下・オフセット左移動ができなくなる (干渉非常解除を入れても動作しない、 E/Gの再始動で動くようになるが再び発生する)	
UNABLE TO OPERATE BOOM or OFFSET TO SWING TO LEFT AFTER RUNNING THE ENGINE FOR A COUPLE OF MINUTES (UNABLE TO OPERATE THEM EVEN TURNING OFF THE ANTI-INTERFERENCE SYSTEM, ABLE TO OPERATE AFTER RESTARTING THE ENGINE BUT HAPPENING THE TROUBLE AGAIN)	
*1 本体ブームとアームで上がらない、ブーム上げ動作: パワー弱い	
*1 UNABLE TO PUSH UP THE BODY BY BOOM, BOOM: WEAK POWER	
*2 エラー表示あり、モード入らない ERROR DISPLAY, CRANE MODE: UNABLE TO TURN ON	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.  
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。