

INSPECTION SHEET 検品書  
EXCAVATOR バックホー

INSPECTION DATE	2026/3/19	MAKE	KOMATSU	MODEL	PC55MR-5
SERIAL	24939		STAMP	KMTPC259VRE024939	
HR METER	638	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / <u>CNP</u> / NONE		SHOE	400G PADS	

**ENGINE : MODEL** 4D88E **S/N** G9325

Oil leakage	<input checked="" type="radio"/> FAIR	Attn	
Blow-By	<input checked="" type="radio"/> FAIR	Attn	A LITTLE · MIDDLE · SEVERE
Sound	<input checked="" type="radio"/> FAIR	Attn	
Oil	<input checked="" type="radio"/> FAIR	Attn	
Exhaust Color	<input checked="" type="radio"/> FAIR	Attn	
US EPA	<input checked="" type="radio"/> YES	NO	

**MAIN PUMP**

Sound	<input checked="" type="radio"/> FAIR	Attn	
Oil leakage	<input checked="" type="radio"/> FAIR	Attn	
Power	<input checked="" type="radio"/> FAIR	Attn	

**COOLING SYSTEM**

Radiator	<input checked="" type="radio"/> FAIR	Attn	
Oil Cooler	<input checked="" type="radio"/> FAIR	Attn	

**OPERATING SYSTEM**

Swing	<input checked="" type="radio"/> FAIR	Attn	
Travel	<input checked="" type="radio"/> FAIR	Attn	

**INTERIOR** See Photos. 写真参照

INTERIOR COND.	<input checked="" type="radio"/> CLEAN	FAIR · DIRTY	
Operator's Seat	<input checked="" type="radio"/> FAIR	Attn	
Glasses	FAIR	Attn	
AirCon	A/C · H/C · H only · C only · <input checked="" type="radio"/> None		

**BOOM / ARM / BKT**

Boom	<input checked="" type="radio"/> FAIR	Attn	
Boom Cylinder	<input checked="" type="radio"/> FAIR	Attn	
Arm	<input checked="" type="radio"/> FAIR	Attn	
Arm Cylinder	<input checked="" type="radio"/> FAIR	Attn	
ATTACHMENT	<input checked="" type="radio"/> FAIR	Attn	
BKT Cylinder	<input checked="" type="radio"/> FAIR	Attn	

**UNDERCARRIAGE :** See Photos. 写真参照

**RUST** (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 4

**COMMENT**

.....

.....

.....

.....

**BKT** STD / SLOPE / NARROW / SKELETON OTHER ( )

**Lever** LONG · WRIST

**Multi** MULTI · 2 · NO

**ARM-CRANE** YES · NO

**BLADE** YES · NO

**OFFSET** YES · NO

**OFFSET Cylinder** FAIR · Attn

**Piping** YES · NO Breaker only · Multi

**COMMENT**

.....

.....

.....

.....

.....

.....

.....

.....

.....

**RUST of BODY** (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 4

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.  
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。