INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2026/3/24	MAKE	HITACHI	MODEL	ZX120-5B
SERIAL	HCMDADA0L00091626		STAMP	HCMDADA0L00091626	
HR METER	4813 HR		YEAR	YR	
CAB/CNP	(ROPS CAB) / CAB / ROPS CNP / CNP / NONE		SHOE	500G PADS	

ENGINE : MODEL 4JJ1 S/N 171504		
Oil leakage	FAIR ・(Attn)	*1
Blow-By	FAIR ・(Attn)	A LITTLE ・(MIDDLE)・ SEVERE
Sound	(FAIR)・ Attn	
Oil	(FAIR)・ Attn	
Exhaust Color	(FAIR)・ Attn	
US EPA	(YES)・ NO	
MAIN PUMP		
Sound	(FAIR)・ Attn	
Oil leakage	(FAIR)・ Attn	
Power	(FAIR)・ Attn	
COOLING SYSTEM		
Radiator	(FAIR)・ Attn	
Oil Cooler	(FAIR)・ Attn	
OPERATING SYSTEM		
Swing	(FAIR)・ Attn	ガタあり SWING: LOOSE
Travel	(FAIR)・ Attn	
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN ・ (FAIR) ・ DIRTY	
Operator's Seat	(FAIR)・ Attn	
Glasses	(FAIR)・ Attn	
AirCon	(A/C) ・ H/C ・ H only ・ C only ・ None	
BOOM / ARM / BKT		
Boom	(FAIR)・ Attn	
Boom Cylinder	(FAIR)・ Attn	
Arm	(FAIR)・ Attn	
Arm Cylinder	(FAIR)・ Attn	
ATTACHMENT	(FAIR)・ Attn	
BKT Cylinder	(FAIR)・ Attn	

UNDERCARRIAGE : See Photos. 写真参照		
RUST(5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3	
COMMENT		
BKT	(STD) / SLOPE / NARROW / SKELETON / OTHER( )	
Lever	LONG ・ (WRIST)	
Multi	(MULTI)・ 2 ・ NO	
ARM-CRANE	(YES)・ NO	
BLADE	YES ・(NO)	
OFFSET	YES ・(NO)	
OFFSET Cylinder	FAIR ・ Attn	
Piping	YES ・(NO)	Breaker only ・ Multi
COMMENT		
*1 ヘッド周りにじみあり AROUND CYLINDER HEAD: OIL OOZING		
RUST of BODY(5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。