

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2026/3/23	MAKE	CAT	MODEL	320DRR-E
SERIAL	CAT0320DERBL01160		STAMP	CAT0320DERBL01160	
HR METER	5206 + 4603	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	600G	

ENGINE : MODEL		S/N
Oil leakage	FAIR · Attn	
Blow-By	FAIR · Attn	A LITTLE · MIDDLE · SEVERE
Sound	FAIR · Attn	
Oil	FAIR · Attn	
Exhaust Color	FAIR · Attn	
US EPA	YES · NO	
MAIN PUMP		
Sound	FAIR · Attn	
Oil leakage	FAIR · Attn	*1
Power	FAIR · Attn	
COOLING SYSTEM		
Radiator	FAIR · Attn	
Oil Cooler	FAIR · Attn	
OPERATING SYSTEM		
Swing	FAIR · Attn	
Travel	FAIR · Attn	
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN · FAIR · DIRTY	
Operator's Seat	FAIR · Attn	破れあり TORN
Glasses	FAIR · Attn	*2
AirCon	A/C · H/C · H only · C only · None	
BOOM / ARM / BKT		
Boom	FAIR · Attn	
Boom Cylinder	FAIR · Attn	*3
Arm	FAIR · Attn	へコミ、ガタあり DENT, LOOSE
Arm Cylinder	FAIR · Attn	
ATTACHMENT	FAIR · Attn	*4
BKT Cylinder	FAIR · Attn	サビ、傷あり RUSTY, SCRATCHED

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
COMMENT	
左側キャリアローラー曲がりあり SOME LEFT CARRIER ROLLER: BENT	
モニター表示暗い MONITOR: BLURRED	
燃料メーター不良 FUEL GAUGE: MALFUNCTION	
BKT	STD / SLOPE / NARROW / SKELETON OTHER ()
Lever	LONG · WRIST
Multi	MULTI · 2 · NO
ARM-CRANE	YES · NO
BLADE	YES · NO
OFFSET	YES · NO
OFFSET Cylinder	FAIR · Attn
Piping	YES · NO Breaker only · Multi *5
COMMENT	
ブーム周りホースひび割れあり SOME HOSES AROUND BOOM: CRACKED	
右サイドカバー変形あり RIGHT SIDE COVER: MUCH DENT	
E/Gオイルレベル低い表示あり(E/Gオイル量OK)	
WARNING DISPLAY FOR LOW ENGINE OIL LEVEL	
(ENGINE OIL LEVEL: ENOUGH)	
*1 ホースひび割れ、にじみあり SOME HOSES: CRACKED, OIL OOZING	
*2 F割れあり、下側欠	
*2 UPPER WINDSHIELD: CRACKED, LOWER WINDSHIELD: MISSING	
*3 左側にじみ、右側油漏れあり	
*3 LEFT CYLINDER: OIL OOZING, RIGHT CYLINDER: OIL LEAKING	
*4 ねじれ、破れ、ガタあり DISTORTED, A LITTLE DAMAGED, LOOSE	
*5 右側ホース欠 RIGHT HOSE: PARTLY MISSING	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。