

**INSPECTION SHEET 検品書**  
**EXCAVATOR バックホー**

INSPECTION DATE	2026/3/19	MAKE	KOMATSU	MODEL	PC78US-11
SERIAL	51364		STAMP	KMTPC297LPA051364	
HR METER	1747	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	450G PADS	

**ENGINE : MODEL** 3D95LE-1 **S/N** 903552

Oil leakage	FAIR	Attn	
Blow-By	FAIR	Attn	A LITTLE · MIDDLE · SEVERE
Sound	FAIR	Attn	
Oil	FAIR	Attn	
Exhaust Color	FAIR	Attn	
US EPA	YES	NO	

**MAIN PUMP**

Sound	FAIR	Attn	
Oil leakage	FAIR	Attn	
Power	FAIR	Attn	

**COOLING SYSTEM**

Radiator	FAIR	Attn	
Oil Cooler	FAIR	Attn	

**OPERATING SYSTEM**

Swing	FAIR	Attn	
Travel	FAIR	Attn	

**INTERIOR See Photos. 写真参照**

INTERIOR COND.	CLEAN	FAIR · DIRTY	
Operator's Seat	FAIR	Attn	
Glasses	FAIR	Attn	
AirCon	A/C	H/C · H only · C only · None	

**BOOM / ARM / BKT**

Boom	FAIR	Attn	2ピースブーム 2-PIECE BOOM (LENGTH: 6.75m)
Boom Cylinder	FAIR	Attn	
Arm	FAIR	Attn	
Arm Cylinder	FAIR	Attn	
ATTACHMENT	FAIR	Attn	ガタあり LOOSE
BKT Cylinder	FAIR	Attn	配管曲がりあり SOME PIPE: BENT

**UNDERCARRIAGE : See Photos. 写真参照**

**RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)** 4

**COMMENT**

BKT	STD / SLOPE / NARROW	SKELETON	OTHER( )
Lever	LONG	WRIST	
Multi	MULTI	2 · NO	

ARM-CRANE YES · NO

BLADE YES · NO

OFFSET YES · NO

OFFSET Cylinder FAIR · Attn

Piping YES · NO Breaker only · Multi 5

**COMMENT**

RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	5	
--	---	--

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。