INSPECTION SHEET 検品書
OTHER その他

INSPECTION DATE	2026/6/1	CATEGORY	VIBRO COMPACTER				
MAKE	MIKASA			MODEL	MVH-100AR		
SERIAL	Z7710			STAMP	NOT FOUND		
HR METER	UNKNOWN HR	Odometer	km	YEAR	YR		
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / (NONE)	SHOE		TIRE			

ENGINE	MODEL		S/N		
Oil leakage	(FAIR) · Attn		Oil	(FAIR) · Attn	
Blow-By	(FAIR) · Attn	A LITTLE · MIDDLE · SEVERE	Exhaust Color	(FAIR) · Attn	
Sound	(FAIR) · Attn		EPA	YES · (NO)	

CONDITION	(FAIR) · Attn	

UNDERCARRIAGE : See Photos. 写真参照			
RUST(5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3	TIRE WEAR	FAIR · WORN · UNEVEN WEAR
COMMENT			
RUST of BODY(5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3		

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。