

INSPECTION SHEET 検品書  
OTHER その他

INSPECTION DATE	2026/6/1	CATEGORY	VIBRO COMPACTER			
MAKE	MIKASA		MODEL	MVH-100AR		
SERIAL	Z7709		STAMP	NOT FOUND		
HR METER	UNKNOWN	HR	Odometer	km	YEAR	YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP		NONE	SHOE	TIRE	

ENGINE	MODEL	S/N
Oil leakage	FAIR · Attn	Oil      FAIR · Attn
Blow-By	FAIR · Attn	A LITTLE · MIDDLE · SEVERE      Exhaust Color      FAIR · Attn
Sound	FAIR · Attn	EPA      YES · NO

CONDITION	FAIR · Attn

**UNDERCARRIAGE : See Photos. 写真参照**

RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3	TIRE WEAR	FAIR · WORN · UNEVEN WEAR
--	---	-----------	---------------------------

**COMMENT**

.....

.....

.....

.....

.....

.....

.....

.....

.....

.....

RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
--	---

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.  
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。