

INSPECTION SHEET 検品書  
EXCAVATOR バックホー

INSPECTION DATE	2026/4/27	MAKE	YANMAR	MODEL	VIO40-5B
SERIAL	58551		STAMP	58551	
HR METER	3536	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / <u>CNP</u> / NONE		SHOE	350G PADS	

**ENGINE : MODEL** 3NNPE **S/N** L3839

Oil leakage	<input checked="" type="radio"/> FAIR	Attn	
Blow-By	<input checked="" type="radio"/> FAIR	Attn	A LITTLE · MIDDLE · SEVERE
Sound	<input checked="" type="radio"/> FAIR	Attn	
Oil	<input checked="" type="radio"/> FAIR	Attn	
Exhaust Color	<input checked="" type="radio"/> FAIR	Attn	
US EPA	<input checked="" type="radio"/> YES	NO	

**MAIN PUMP**

Sound	<input checked="" type="radio"/> FAIR	Attn	
Oil leakage	<input checked="" type="radio"/> FAIR	Attn	ホース油漏れ小 SOME HOSE: OIL LEAKING
Power	<input checked="" type="radio"/> FAIR	Attn	

**COOLING SYSTEM**

Radiator	<input checked="" type="radio"/> FAIR	Attn	
Oil Cooler	<input checked="" type="radio"/> FAIR	Attn	

**OPERATING SYSTEM**

Swing	<input checked="" type="radio"/> FAIR	Attn	
Travel	<input checked="" type="radio"/> FAIR	Attn	

**INTERIOR** See Photos. 写真参照

INTERIOR COND.	CLEAN	<input checked="" type="radio"/> FAIR	DIRTY
Operator's Seat	<input checked="" type="radio"/> FAIR	Attn	破れあり CUTS
Glasses	<input checked="" type="radio"/> FAIR	Attn	
AirCon	A/C	H/C	H only · C only · <input checked="" type="radio"/> None

**BOOM / ARM / BKT**

Boom	<input checked="" type="radio"/> FAIR	Attn	
Boom Cylinder	<input checked="" type="radio"/> FAIR	Attn	
Arm	<input checked="" type="radio"/> FAIR	Attn	
Arm Cylinder	<input checked="" type="radio"/> FAIR	Attn	
ATTACHMENT	<input checked="" type="radio"/> FAIR	Attn	
BKT Cylinder	<input checked="" type="radio"/> FAIR	Attn	

**UNDERCARRIAGE :** See Photos. 写真参照

RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 3

**COMMENT**

.....

.....

.....

.....

BKT  STD / SLOPE / NARROW / SKELETON / OTHER ( )

Lever LONG ·  WRIST

Multi  MULTI · 2 · NO

ARM-CRANE YES ·  NO

BLADE  YES · NO

OFFSET YES ·  NO

OFFSET Cylinder FAIR · Attn

Piping YES ·  NO Breaker only · Multi

**COMMENT**

.....

.....

.....

.....

RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.  
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。