INSPECTION SHEET 検品書
WHEEL LOADER タイヤショベル

INSPECTION DATE	2026/4/2	MAKE	CAT	MODEL	259D
SERIAL	CAT0259DPFTL01502		STAMP	UNREADABLE	
HR METER	3989 HR	Odometer	– km	YEAR	YR
CAB/CNP	ROPS CAB / CAB / (ROPS CNP) / CNP / NONE		TIRE SIZE	–	

ENGINE : MODEL C3.3B S/N 8EA3574		
Oil leakage	(FAIR) · Attn	
Blow-By	(FAIR) · Attn	A LITTLE · MIDDLE · SEVERE
Sound	(FAIR) · Attn	
Oil	(FAIR) · Attn	
Exhaust Color	(FAIR) · Attn	
US EPA	(YES) · NO	
OPERATION PUMP		
Sound	(FAIR) · Attn	
Oil leakage	(FAIR) · Attn	
Power	(FAIR) · Attn	
COOLING SYSTEM		
Radiator	(FAIR) · Attn	
Oil Cooler	(FAIR) · Attn	
TRANSMISSION & TRAVEL		
T/M TYPE	(PS) · DD	
Transmission	(FAIR) · Attn	
Travel	(FAIR) · Attn	
FOOT BRAKE	FAIR · Attn	
PARKING BRAKE	(FAIR) · Attn	
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN · (FAIR) · DIRTY	
Operator's Seat	(FAIR) · Attn	破れあり CUTS
Glasses	FAIR · Attn	
AirCon	A/C · H/C · H only · C only · (None)	
FRONT & CYLINDERS		
Arm	(FAIR) · Attn	
Bell crank	(FAIR) · Attn	
Bucket	(FAIR) · Attn	
Articulate	FAIR · Attn	

UNDERCARRIAGE : See Photos. 写真参照			
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			4
TIRE WEAR	FAIR · WORN · UNEVEN WEAR		
COMMENT			
SHOE: 320R			
STEERING TYPE	WHEEL STEERING / COMMAND STEERING / (LEVER STEERING)		
RIDE CONTROL	(YES) · NO		
ATTACHMENTS			
STD BKT	YES · (OTHER)	フォーク FORK (LENGTH: 1200mm)	
BLADE	YES · (NO)	Piping for Tilt (YES) · NO	
COMMENT			
アーム周りホースひび割れあり SOME HOSE AROUND ARMS: CRACKED			
E875-2表示、！マーク表示あり			
"E875-2" ERROR DISPLAY, WARNING LAMP: ON			
付属品：バケット BUCKET AS SPARE			
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			4

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。