INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2026/3/30	MAKE	CAT	MODEL	320B
SERIAL	3MR07534		STAMP	3MR07534	
HR METER	13899 HR		YEAR	YR	
CAB/CNP	ROPS CAB / (CAB) / ROPS CNP / CNP / NONE		SHOE	600G	

ENGINE : MODEL	S/N 7JK41551	
Oil leakage	FAIR ・(Attn)	*1
Blow-By	(FAIR)・ Attn	A LITTLE・ MIDDLE・ SEVERE
Sound	(FAIR)・ Attn	
Oil	(FAIR)・ Attn	
Exhaust Color	(FAIR)・ Attn	
US EPA	YES ・(NO)	
MAIN PUMP		
Sound	(FAIR)・ Attn	
Oil leakage	FAIR ・(Attn)	ホースにじみあり SOME HOSE: OIL OOZING
Power	(FAIR)・ Attn	
COOLING SYSTEM		
Radiator	(FAIR)・ Attn	
Oil Cooler	(FAIR)・ Attn	
OPERATING SYSTEM		
Swing	(FAIR)・ Attn	
Travel	(FAIR)・ Attn	
INTERIOR	**See Photos. 写真参照**	
INTERIOR COND.	CLEAN ・ (FAIR) ・ DIRTY	
Operator's Seat	(FAIR)・ Attn	
Glasses	(FAIR)・ Attn	
AirCon	(A/C) ・ H/C ・ H only ・ C only ・ None	
BOOM / ARM / BKT		
Boom	(FAIR)・ Attn	
Boom Cylinder	(FAIR)・ Attn	
Arm	(FAIR)・ Attn	
Arm Cylinder	FAIR ・(Attn)	油漏れあり OIL LEAKING
ATTACHMENT	(FAIR)・ Attn	
BKT Cylinder	FAIR ・(Attn)	油漏れ小 OIL LEAKING

UNDERCARRIAGE :	See Photos. 写真参照	
RUST(5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		3
COMMENT		
左右シューリンク固着あり TRACK LINKS: STUCK		
BKT	STD / (SLOPE) / NARROW / SKELETON / OTHER( )	
Lever	LONG ・ (WRIST)	
Multi	MULTI ・ 2 ・ (NO)	
ARM-CRANE	YES ・(NO)	
BLADE	YES ・(NO)	
OFFSET	YES ・(NO)	
OFFSET Cylinder	FAIR ・ Attn	
Piping	(YES) ・ NO	Breaker only ・ (Multi)
COMMENT		
旋回モーター周り油汚れあり AROUND SWING MOTOR: OIL STAINS		
*1 ヘッドカバー周りにじみ、オイルパン周り油漏れあり		
*1 AROUND HEAD COVER: OIL OOZING, AROUND OIL PAN: OIL LEAKING		
RUST of BODY(5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。