

INSPECTION SHEET 検品書
GENERATOR / COMPRESSOR / WELDER 発電機・コンプレッサー・ウェルダ

INSPECTION DATE	2026/3/25	CATEGORY	GENERATOR / COMPRESSOR / WELDER		
MAKE	DENYO		MODEL	DCA-750SGC-H	
SERIAL	3891026		STAMP	NOT FOUND	
HR METER	UNKNOWN	HR	TIRE SIZE	-	YEAR YR

ENGINE :	MODEL	SA12V140	S/N	17655	
Oil leakage	FAIR · Attn	ブロック割れ大 ENGINE BLOCK: MUCH CRACKED	Oil	FAIR · Attn	*2
Blow-By	FAIR · Attn	A LITTLE · MIDDLE · SEVERE *1	Exhaust Color	FAIR · Attn	*1
Sound	FAIR · Attn	*1	Radiator	FAIR · Attn	水量不足 COOLANT LEVEL: NOT ENOUGH

GENERATOR					
RATED POWER	750	KVA	Leaking Breaker Condition	FAIR · Attn	*1
RATED AMPERE	984	A	Insulation Condition	FAIR · Attn	*1
Output Terminal	FAIR · Attn				

COMPRESSOR					
RATED PRESSURE		Mpa Kgf/cm2	Unload Condition	FAIR · Attn	
RATED AIR FLOW		m3/min	Receiver Tank Condition	FAIR · Attn	
Compressor Oil Leak	FAIR · Attn		Safety Valve Condition	FAIR · Attn	

CONDITION	FAIR · Attn	
E/Gブローのため動作不可、動作未確認 OPERATION: NOT CHECKED (ENGINE BLOW-UP)		

RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	5	TIRE WEAR	FAIR · WORN · UNEVEN WEAR
--	---	-----------	---------------------------

COMMENTS			
確認ができる範囲でE/Gブロック割れ、穴、コンロッド破損、E/G内金属片混入、傷、クランクシャフトカウンターウエイト削れあり			
ENGINE BLOCK: MUCH CRACKED, HUGE HOLES, CONNECTING ROD: BROKEN,			
METAL FRAGMENTS: ENTERING THE ENGINE, A LITTLE DAMAGED,			
CRANKSHAFT COUNTERWEIGHT: A LITTLE DAMAGED (AS FAR AS WE CAN CHECK)			
オイルフィルター外れあり OIL FILTER: COME OFF			
*1 未確認 NOT CHECKED			
*2 白濁、水混入あり、油量不良 CLOUDY (WATER: MIXED), ENGINE OIL LEVEL: NOT ENOUGH			

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
 この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。