INSPECTION SHEET 検品書
LIFTING PLATFORM 高所作業車

INSPECTION DATE	2026/3/25	MAKE	MAEDA	MODEL	HF090-3
SERIAL No.	PLATE : 9HF3733		STAMP : NU0930733		
HR METER	4519 HR	Odometer	– km	YEAR	YR
CHASSIS	MODEL –		No. –		
SHOE	300R		TIRE SIZE		
MAX HIGHT	9.1 m		MAX WEIGHT	200 kg	

ENGINE : MODEL S/N		
Oil leakage	(FAIR) · Attn	
Blow-By	(FAIR) · Attn	A LITTLE · MIDDLE · SEVERE
Sound	(FAIR) · Attn	
Oil	(FAIR) · Attn	
Exhaust Color	(FAIR) · Attn	
US EPA	YES · (NO)	
OPERATION PUMP		
Sound	(FAIR) · Attn	
Oil leakage	(FAIR) · Attn	
Power	(FAIR) · Attn	
COOLING SYSTEM		
Radiator	(FAIR) · Attn	
Oil Cooler	FAIR · Attn	
TRANSMISSION & TRAVEL		
T/M TYPE	(AT) · MT	No. OF GEARS 1 GEARS
Transmission	(FAIR) · Attn	
4WD	4WD · 2WD	
Travel	(FAIR) · Attn	
Swing	(FAIR) · Attn	
FOOT BRAKE	FAIR · Attn	
PARKING BRAKE	FAIR · Attn	
BOOM		
No. of Section	2 SECTIONS	
DERRICKING CYL.	(FAIR) · Attn	
EXTENSION CYL.	(FAIR) · Attn	

INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN · FAIR · DIRTY	
Operator's Seat	FAIR · Attn	
Glasses	FAIR · Attn	
AirCon	A/C · H/C · H only · C only · (None)	
UNDERCARRIAGE : See Photos. 写真参照		
RUST(5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		4
TIRE WEAR	FAIR · WORN · UNEVEN WEAR	
COMMENT		
OUTRIGGERS	X · H	
OUTRIGGERS COND.	FAIR · Attn	
COMMENT		
RUST of BODY(5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		4

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。