

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2026/4/1	MAKE	HITACHI	MODEL	EX300LC
SERIAL	159-4630		STAMP	159-4630	
HR METER	2744	HR	YEAR	YR	
CAB/CNP	ROPS CAB / <u>CAB</u> / ROPS CNP / CNP / NONE		SHOE	600G	

ENGINE : MODEL		S/N
Oil leakage	<u>FAIR</u> · Attn	
Blow-By	<u>FAIR</u> · <u>Attn</u>	A LITTLE · <u>MIDDLE</u> · SEVERE
Sound	<u>FAIR</u> · Attn	
Oil	<u>FAIR</u> · Attn	
Exhaust Color	<u>FAIR</u> · Attn	
US EPA	YES · <u>NO</u>	
MAIN PUMP		
Sound	<u>FAIR</u> · Attn	
Oil leakage	<u>FAIR</u> · Attn	
Power	<u>FAIR</u> · Attn	
COOLING SYSTEM		
Radiator	<u>FAIR</u> · Attn	
Oil Cooler	<u>FAIR</u> · Attn	
OPERATING SYSTEM		
Swing	<u>FAIR</u> · Attn	ガタあり SWING: LOOSE
Travel	<u>FAIR</u> · Attn	*1
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN · <u>FAIR</u> · DIRTY	
Operator's Seat	<u>FAIR</u> · Attn	
Glasses	<u>FAIR</u> · Attn	
AirCon	A/C · H/C · <u>H only</u> · C only · None	
BOOM / ARM / BKT		
Boom	<u>FAIR</u> · Attn	中間ブームガタあり INSERT BOOM: LOOSE
Boom Cylinder	<u>FAIR</u> · <u>Attn</u>	*2
Arm	<u>FAIR</u> · Attn	
Arm Cylinder	<u>FAIR</u> · Attn	
ATTACHMENT	<u>FAIR</u> · Attn	
BKT Cylinder	<u>FAIR</u> · <u>Attn</u>	にじみ、傷あり OIL OOZING, SCRATCHED

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
COMMENT	
BKT	STD / SLOPE / NARROW / SKELETON / OTHER ()
Lever	LONG · <u>WRIST</u>
Multi	<u>MULTI</u> · 2 · NO *3
ARM-CRANE	YES · <u>NO</u>
BLADE	YES · <u>NO</u>
OFFSET	YES · <u>NO</u>
OFFSET Cylinder	<u>FAIR</u> · Attn
Piping	<u>YES</u> · NO Breaker only · Multi 5 *4
COMMENT	
旋回モーターにじみあり SWING MOTOR: OIL OOZING コントロールバルブ油漏れ小 CONTROL VALVE: OIL LEAKING ブーム周りホースひび割れあり SOME HOSES AROUND BOOM: MUCH CRACKED 3段ブーム 3-SECTION BOOM アタッチメントなし WITHOUT ATTACHMENT *1 HI/LO切替え不良、少しずつ右に曲がる *1 HI/LO SWITCH: MALFUNCTION, A LITTLE TOTTERING TO RIGHT *2 右側シリンダー下側配管ホースにじみあり *2 LOWER HOSE OF RIGHT CYLINDER: OIL OOZING *3 ホースにじみあり SOME HOSES: OIL OOZING *4 油漏れあり OIL LEAKING	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
 この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。