INSPECTION SHEET 検品書

ASPHALT FINISHER　アスファルトフィニッシャー

INSPECTION DATE	2026/3/31	MAKE	SUMITOMO	MODEL	HA60W-5
SERIAL	A60A5-0346		STAMP	A60A5-0346	
HR METER	63 + 4878 HR		YEAR	YR	
SHOE		TIRE (REAR)	15.5R25	MAX PAVING WIDTH	6150 mm

ENGINE : MODEL	S/N	
Oil leakage	(FAIR) · Attn	
Blow-By	(FAIR) · Attn	A LITTLE · MIDDLE · SEVERE
Sound	(FAIR) · Attn	
Oil	(FAIR) · Attn	
Exhaust Color	(FAIR) · Attn	
US EPA	YES · (NO)	
OPERATION PUMP		
Sound	(FAIR) · Attn	
Oil leakage	(FAIR) · Attn	
Power	(FAIR) · Attn	
COOLING SYSTEM		
Radiator	(FAIR) · Attn	
Oil Cooler	(FAIR) · Attn	
OPERATING SYSTEM		
TRAVEL	(FAIR) · Attn	
SCREED(R)	FAIR · (Attn)	*1
SCREED(L)	FAIR · (Attn)	*1
VIBRATION	(FAIR) · Attn	
TAMPER	FAIR · Attn	
SPREADER(R)	(FAIR) · Attn	
SPREADER(L)	(FAIR) · Attn	
HOPPER(R)	(FAIR) · Attn	
HOPPER(L)	(FAIR) · Attn	
FEEDER	(FAIR) · Attn	

UNDERCARRIAGE :　See Photos. 写真参照

RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
TIRE WEAR	(FAIR) · WORN · UNEVEN WEAR

COMMENT

左Rタイヤ:エアー少ない　REAR LEFT TIRE: LOW TIRE PRESSURE

SCREED WIDTH

MAIN SCREED	2.5	m
WITH AUTO-WIDENER		m
WITH EXTENSION	6.15	m
LEVEL SENSOR	YES · (NO)	

COMMENT

CNP

リペイントあり　REPAINTED

左レベリングシリンダー油漏れ小　LEFT LEVELING CYLINDER: OIL LEAKING

ホッパー内部材あり　SOME PARTS: PUTTING IN HOPPER

*1 シリンダーメッキ剥がれ、サビあり　CYLINDER: COATING PEELED, RUSTY

RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。