

INSPECTION SHEET 検品書  
ROUGH TERRAIN CRANE ラフタークレーン

INSPECTION DATE	2026/4/6	MAKE	TADANO	MODEL	TR-250M-6
SERIAL No.	PLATE : FB2435		STAMP : TR255-0963		
HR METER	15591	HR	Odometer	40353	km
TIRE SIZE	385/95R25		YEAR	YR	

**ENGINE : MODEL S/N**

Oil leakage	FAIR <input checked="" type="radio"/> Attn	ヘッド油漏れあり CYLINDER HEAD: OIL LEAKING
Blow-By	FAIR <input checked="" type="radio"/> Attn	A LITTLE · MIDDLE · SEVERE
Sound	FAIR <input checked="" type="radio"/> Attn	
Oil	FAIR <input checked="" type="radio"/> Attn	
Exhaust Color	FAIR <input checked="" type="radio"/> Attn	

**OPERATION PUMP**

Sound	FAIR <input checked="" type="radio"/> Attn	
Oil leakage	FAIR <input checked="" type="radio"/> Attn	
Power	FAIR <input checked="" type="radio"/> Attn	

**COOLING SYSTEM**

Radiator	FAIR <input checked="" type="radio"/> Attn	
Oil Cooler	FAIR <input checked="" type="radio"/> Attn	

**OPERATING SYSTEM**

Computer	OK <input checked="" type="radio"/> NG	
Swing	FAIR <input checked="" type="radio"/> Attn	
Travel	FAIR <input checked="" type="radio"/> Attn	

**TRANSMISSION**

Transmission	FAIR <input checked="" type="radio"/> Attn	
No. OF GEARS	4 GEARS	
4WD	4WD <input checked="" type="radio"/> 6WD	

**INTERIOR See Photos. 写真参照**

INTERIOR COND.	CLEAN · FAIR <input checked="" type="radio"/> DIRTY	
Operator's Seat	FAIR <input checked="" type="radio"/> Attn	
Glasses	FAIR <input checked="" type="radio"/> Attn	
AirCon	A/C <input checked="" type="radio"/> H/C · H only · C only · None	

**COMMENT**


**BOOM**

No. of Section	4 SECTIONS	
CRACK/ENFORCEMENT	FAIR <input checked="" type="radio"/> Attn	
DERRICKING CYL.	FAIR <input checked="" type="radio"/> Attn *1	
EXTENSION CYL.	FAIR <input checked="" type="radio"/> Attn	
JIB	YES <input checked="" type="radio"/> NO	
JIB TYPE	STD <input checked="" type="radio"/> PWR	
MAIN & SUB WIRE	YES <input checked="" type="radio"/> NO	
FREE FALL	YES <input checked="" type="radio"/> NO	
HOOK	12t, BALL	

**UNDERCARRIAGE : See Photos. 写真参照**

RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	1
TIRE WEAR	FAIR <input checked="" type="radio"/> WORN · UNEVEN WEAR

**COMMENT**

フェンダー上部穴あり TOP OF SOME FENDERS: HOLES

**OUTRIGGERS**

OUTRIGGERS	X · H <input checked="" type="radio"/>	
OUTRIGGERS COND.	FAIR <input checked="" type="radio"/> Attn	
Oil leakage (JACK CYL.)	FRONT	L · R REAR L · R
Oil leakage (SLIDE CYL.)	FRONT	L · R REAR L · R

**COMMENT**

メインフック欠 NO MAIN HOOK
ホースリール変形あり HOSE REEL: A LITTLE DEFORMED
*1 油漏れ、自然降下あり OIL LEAKING, HYDRAULIC DRIFT

**COMMENT**

RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	1
--	---

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.  
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。