

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2026/4/1	MAKE	KOBELCO	MODEL	SK75SRD-3E
SERIAL	YT08-35115		STAMP	YT08-35115	
HR METER	UNKNOWN		HR	YEAR	YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	450G PADS	

ENGINE : MODEL 4LE2 S/N 691975	
Oil leakage	☒ FAIR · Attn
Blow-By	☒ FAIR · Attn A LITTLE · MIDDLE · SEVERE
Sound	☒ FAIR · Attn
Oil	☒ FAIR · Attn
Exhaust Color	☒ FAIR · Attn
US EPA	☒ YES · NO
MAIN PUMP	
Sound	☒ FAIR · Attn
Oil leakage	☒ FAIR · Attn
Power	☒ FAIR · Attn
COOLING SYSTEM	
Radiator	☒ FAIR · Attn
Oil Cooler	☒ FAIR · Attn
OPERATING SYSTEM	
Swing	☒ FAIR · Attn
Travel	☒ FAIR · Attn
INTERIOR See Photos. 写真参照	
INTERIOR COND.	CLEAN · ☒ FAIR · DIRTY
Operator's Seat	☒ FAIR · ☒ Attn 破れあり CUT
Glasses	☒ FAIR · Attn
AirCon	☒ A/C · H/C · H only · C only · None
BOOM / ARM / BKT	
Boom	☒ FAIR · Attn
Boom Cylinder	☒ FAIR · Attn
Arm	☒ FAIR · Attn
Arm Cylinder	☒ FAIR · Attn
ATTACHMENT	☒ FAIR · Attn
BKT Cylinder	☒ FAIR · Attn

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
COMMENT	
BKT	☒ STD / ☐ SLOPE / ☐ NARROW / ☐ SKELETON / OTHER ()
Lever	LONG · ☒ WRIST
Multi	☒ MULTI · 2 · NO
ARM-CRANE	YES · ☒ NO
BLADE	☒ YES · NO
OFFSET	YES · ☒ NO
OFFSET Cylinder	FAIR · Attn
Piping	☒ YES · NO Breaker only · Multi 5
COMMENT	
HRメーター故障あり HR METER: MALFUNCTION	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。