

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2026/3/26	MAKE	HITACHI	MODEL	ZX210K-5B
SERIAL	HCMDCKA6J00300926		STAMP	HCMDCKA6J00300926	
HR METER	6880	HR	YEAR	2014	YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	600G	

ENGINE : MODEL 4HK1 **S/N** 715900

Oil leakage	FAIR	Attn	
Blow-By	FAIR	Attn	A LITTLE · MIDDLE · SEVERE
Sound	FAIR	Attn	
Oil	FAIR	Attn	
Exhaust Color	FAIR	Attn	
US EPA	YES	NO	

MAIN PUMP

Sound	FAIR	Attn	
Oil leakage	FAIR	Attn	配管にじみあり SOME PIPE: OIL OOZING
Power	FAIR	Attn	

COOLING SYSTEM

Radiator	FAIR	Attn	オイル混入あり OIL: MIXED
Oil Cooler	FAIR	Attn	油汚れあり OIL STAINS

OPERATING SYSTEM

Swing	FAIR	Attn	
Travel	FAIR	Attn	

INTERIOR See Photos. 写真参照

INTERIOR COND.	CLEAN	FAIR	DIRTY
Operator's Seat	FAIR	Attn	破れあり CUT
Glasses	FAIR	Attn	
AirCon	A/C	H/C	H only · C only · None

BOOM / ARM / BKT

Boom	FAIR	Attn	
Boom Cylinder	FAIR	Attn	
Arm	FAIR	Attn	ガタあり LOOSE
Arm Cylinder	FAIR	Attn	
ATTACHMENT	FAIR	Attn	ガタあり LOOSE
BKT Cylinder	FAIR	Attn	

UNDERCARRIAGE : See Photos. 写真参照

RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 3

COMMENT

カウンターウエイトリペイントあり COUNTERWEIGHT: REPAINTED
エアクリーナー周りホースにじみあり
SOME HOSE AROUND AIR CLEANER: OIL OOZING
*1 右側にじみあり RIGHT PIPE: OIL OOZING

BKT	STD / SLOPE / NARROW	SKELETON	OTHER ()
Lever	LONG	WRIST	
Multi	MULTI	2	NO
ARM-CRANE	YES	NO	
BLADE	YES	NO	
OFFSET	YES	NO	
OFFSET Cylinder	FAIR	Attn	
Piping	YES	NO	Breaker only · Multi *1

COMMENT

カウンターウエイトリペイントあり COUNTERWEIGHT: REPAINTED
エアクリーナー周りホースにじみあり
SOME HOSE AROUND AIR CLEANER: OIL OOZING
*1 右側にじみあり RIGHT PIPE: OIL OOZING

カウンターウエイトリペイントあり COUNTERWEIGHT: REPAINTED
エアクリーナー周りホースにじみあり
SOME HOSE AROUND AIR CLEANER: OIL OOZING
*1 右側にじみあり RIGHT PIPE: OIL OOZING

RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 4

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。