

INSPECTION SHEET 検品書
ROUGH TERRAIN CRANE ラフタークレーン

| | | | | | |
|-----------------|----------------|------|--------------------|--------|-----------|
| INSPECTION DATE | 2026/3/27 | MAKE | TADANO | MODEL | TR-100M-1 |
| SERIAL No. | PLATE : FC0530 | | STAMP : TR100-0530 | | |
| HR METER | 2612 | HR | Odometer | 113765 | km |
| TIRE SIZE | 11R22.5 16PR | | YEAR | YR | |

| ENGINE : MODEL | S/N |
|----------------------------------|---|
| Oil leakage | <input type="radio"/> FAIR · <input type="radio"/> Attn |
| Blow-By | <input type="radio"/> FAIR · <input type="radio"/> Attn A LITTLE · MIDDLE · <input checked="" type="radio"/> SEVERE |
| Sound | <input type="radio"/> FAIR · <input type="radio"/> Attn |
| Oil | <input type="radio"/> FAIR · <input type="radio"/> Attn |
| Exhaust Color | <input type="radio"/> FAIR · <input type="radio"/> Attn |
| OPERATION PUMP | |
| Sound | <input type="radio"/> FAIR · <input type="radio"/> Attn |
| Oil leakage | <input type="radio"/> FAIR · <input type="radio"/> Attn |
| Power | <input type="radio"/> FAIR · <input type="radio"/> Attn |
| COOLING SYSTEM | |
| Radiator | <input type="radio"/> FAIR · <input type="radio"/> Attn |
| Oil Cooler | <input type="radio"/> FAIR · <input type="radio"/> Attn |
| OPERATING SYSTEM | |
| Computer | <input checked="" type="radio"/> OK · <input type="radio"/> NG |
| Swing | <input type="radio"/> FAIR · <input type="radio"/> Attn |
| Travel | <input type="radio"/> FAIR · <input type="radio"/> Attn |
| TRANSMISSION | |
| Transmission | <input type="radio"/> FAIR · <input type="radio"/> Attn |
| No. OF GEARS | 3 GEARS |
| 4WD | <input checked="" type="radio"/> 4WD · <input type="radio"/> 6WD |
| INTERIOR See Photos. 写真参照 | |
| INTERIOR COND. | CLEAN · <input checked="" type="radio"/> FAIR · <input type="radio"/> DIRTY |
| Operator's Seat | <input type="radio"/> FAIR · <input type="radio"/> Attn 破れあり SEAT COVER: HUGE CUTS |
| Glasses | <input type="radio"/> FAIR · <input type="radio"/> Attn |
| AirCon | <input checked="" type="radio"/> A/C · <input type="radio"/> H/C · <input type="radio"/> H only · <input type="radio"/> C only · <input type="radio"/> None |
| COMMENT | |
| | |

| BOOM | |
|--|--|
| No. of Section | 6 SECTIONS |
| CRACK/ENFORCEMENT | <input type="radio"/> FAIR · <input type="radio"/> Attn |
| DERRICKING CYL. | <input type="radio"/> FAIR · <input type="radio"/> Attn |
| EXTENSION CYL. | <input type="radio"/> FAIR · <input type="radio"/> Attn |
| JIB | YES · <input checked="" type="radio"/> NO |
| JIB TYPE | STD · <input type="radio"/> PWR |
| MAIN & SUB WIRE | <input checked="" type="radio"/> YES · <input type="radio"/> NO |
| FREE FALL | <input checked="" type="radio"/> YES · <input type="radio"/> NO |
| HOOK | 10t, BALL |
| UNDERCARRIAGE : See Photos. 写真参照 | |
| RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 2: CORRODED) | 4 |
| TIRE WEAR | <input checked="" type="radio"/> FAIR · <input type="radio"/> WORN · <input type="radio"/> UNEVEN WEAR |
| COMMENT | |
| 右タイヤハブシール油漏れあり FRONT RIGHT HUB SEAL: OIL LEAKING | |
| OUTRIGGERS | |
| OUTRIGGERS | <input checked="" type="radio"/> X · <input type="radio"/> H |
| OUTRIGGERS COND. | <input type="radio"/> FAIR · <input type="radio"/> Attn |
| Oil leakage (JACK CYL.) | FRONT L · <input type="radio"/> R REAR L · <input type="radio"/> R |
| Oil leakage (SLIDE CYL.) | FRONT L · <input type="radio"/> R REAR L · <input type="radio"/> R |
| COMMENT | |
| | |
| RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) | 4 |

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。