

**INSPECTION SHEET 検品書**  
**ROUGH TERRAIN CRANE ラフタークレーン**

INSPECTION DATE	2026/3/27	MAKE	KATO	MODEL	KR-50H-F
SERIAL No.	PLATE :	01A0081		STAMP :	KRC016-0081
HR METER	17956	HR	Odometer	60663	km
TIRE SIZE	385/95R25		YEAR	YR	

ENGINE : MODEL	S/N
Oil leakage	<input checked="" type="radio"/> FAIR · Attn
Blow-By	<input checked="" type="radio"/> FAIR · Attn A LITTLE · MIDDLE · SEVERE
Sound	<input checked="" type="radio"/> FAIR · Attn
Oil	<input checked="" type="radio"/> FAIR · Attn
Exhaust Color	<input checked="" type="radio"/> FAIR · Attn
<b>OPERATION PUMP</b>	
Sound	<input checked="" type="radio"/> FAIR · Attn
Oil leakage	<input checked="" type="radio"/> FAIR · Attn
Power	<input checked="" type="radio"/> FAIR · Attn
<b>COOLING SYSTEM</b>	
Radiator	<input checked="" type="radio"/> FAIR · Attn
Oil Cooler	<input checked="" type="radio"/> FAIR · Attn
<b>OPERATING SYSTEM</b>	
Computer	<input checked="" type="radio"/> OK · NG
Swing	<input checked="" type="radio"/> FAIR · Attn
Travel	<input checked="" type="radio"/> FAIR · Attn
<b>TRANSMISSION</b>	
Transmission	<input checked="" type="radio"/> FAIR · Attn
No. OF GEARS	4 GEARS
4WD	<input checked="" type="radio"/> 4WD · 6WD
<b>INTERIOR See Photos. 写真参照</b>	
INTERIOR COND.	CLEAN · <input checked="" type="radio"/> FAIR · DIRTY
Operator's Seat	<input checked="" type="radio"/> FAIR · Attn
Glasses	<input checked="" type="radio"/> FAIR · Attn
AirCon	<input checked="" type="radio"/> A/C · H/C · H only · C only · None
<b>COMMENT</b>	

BOOM	
No. of Section	5 SECTIONS
CRACK/ENFORCEMENT	<input checked="" type="radio"/> FAIR · Attn
DERRICKING CYL.	<input checked="" type="radio"/> FAIR · Attn
EXTENSION CYL.	<input checked="" type="radio"/> FAIR · Attn
JIB	<input checked="" type="radio"/> YES · NO
JIB TYPE	STD · <input checked="" type="radio"/> PWR
MAIN & SUB WIRE	<input checked="" type="radio"/> YES · NO
FREE FALL	YES · <input checked="" type="radio"/> NO
HOOK	50t, 34t, BALL
<b>UNDERCARRIAGE : See Photos. 写真参照</b>	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 2: CORRODED)	4
TIRE WEAR	<input checked="" type="radio"/> FAIR · WORN · UNEVEN WEAR
<b>COMMENT</b>	
<b>OUTRIGGERS</b>	
OUTRIGGERS	X · <input checked="" type="radio"/> H
OUTRIGGERS COND.	<input checked="" type="radio"/> FAIR · Attn
Oil leakage (JACK CYL.)	FRONT L · R REAR L · R
Oil leakage (SLIDE CYL.)	FRONT L · R REAR L · R
<b>COMMENT</b>	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.  
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。