

**INSPECTION SHEET 検品書**  
**ROUGH TERRAIN CRANE ラフタークレーン**

INSPECTION DATE	2026/4/6	MAKE	KATO	MODEL	KR-65H
SERIAL No.	PLATE :	0311148		STAMP :	KRC002-1148
HR METER	34966	HR	Odometer	118576	km
TIRE SIZE	505/95R25		YEAR	YR	

<b>ENGINE : MODEL</b>		<b>S/N</b>
Oil leakage	<input checked="" type="radio"/> FAIR · Attn	
Blow-By	<input checked="" type="radio"/> FAIR · Attn	A LITTLE · MIDDLE · SEVERE
Sound	<input checked="" type="radio"/> FAIR · Attn	
Oil	<input checked="" type="radio"/> FAIR · Attn	
Exhaust Color	<input checked="" type="radio"/> FAIR · Attn	
<b>OPERATION PUMP</b>		
Sound	<input checked="" type="radio"/> FAIR · Attn	
Oil leakage	<input checked="" type="radio"/> FAIR · Attn	
Power	<input checked="" type="radio"/> FAIR · Attn	
<b>COOLING SYSTEM</b>		
Radiator	<input checked="" type="radio"/> FAIR · Attn	
Oil Cooler	<input checked="" type="radio"/> FAIR · Attn	
<b>OPERATING SYSTEM</b>		
Computer	<input checked="" type="radio"/> OK · NG	
Swing	<input checked="" type="radio"/> FAIR · Attn	
Travel	<input checked="" type="radio"/> FAIR · Attn	
<b>TRANSMISSION</b>		
Transmission	<input checked="" type="radio"/> FAIR · Attn	*1
No. OF GEARS	4	GEARS
4WD	<input checked="" type="radio"/> 4WD · 6WD	
<b>INTERIOR See Photos. 写真参照</b>		
INTERIOR COND.	CLEAN · <input checked="" type="radio"/> FAIR · DIRTY	
Operator's Seat	<input checked="" type="radio"/> FAIR · Attn	
Glasses	<input checked="" type="radio"/> FAIR · Attn	
AirCon	<input checked="" type="radio"/> A/C · H/C · H only · C only · None	
<b>COMMENT</b>		

<b>BOOM</b>			
No. of Section	6	SECTIONS	
CRACK/ENFORCEMENT	<input checked="" type="radio"/> FAIR · Attn		
DERRICKING CYL.	<input checked="" type="radio"/> FAIR · Attn		
EXTENSION CYL.	<input checked="" type="radio"/> FAIR · Attn		
JIB	<input checked="" type="radio"/> YES · NO		
JIB TYPE	STD · <input checked="" type="radio"/> PWR		
MAIN & SUB WIRE	<input checked="" type="radio"/> YES · NO		
FREE FALL	YES · <input checked="" type="radio"/> NO		
HOOK	65t, 25t, BALL		
<b>UNDERCARRIAGE : See Photos. 写真参照</b>			
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			2
TIRE WEAR		<input checked="" type="radio"/> FAIR · WORN · UNEVEN WEAR	
<b>COMMENT</b>			
<b>OUTRIGGERS</b>			
OUTRIGGERS	X · <input checked="" type="radio"/> H		
OUTRIGGERS COND.	<input checked="" type="radio"/> FAIR · Attn		
Oil leakage (JACK CYL.)	FRONT	L · R	REAR L · R
Oil leakage (SLIDE CYL.)	FRONT	L · R	REAR L · R
<b>COMMENT</b>			
シーブブロック欠 SHEAVE BLOCK: MISSING			
*1 トルコン付近油漏れあり AROUND TORQUE CONVERTER: OIL LEAKING			
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			4

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.  
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。