

INSPECTION SHEET 検品書
ROUGH TERRAIN CRANE ラフタークレーン

INSPECTION DATE	2026/5/27	MAKE	TADANO	MODEL	GR-250N-1
SERIAL No.	PLATE : FB4454		STAMP : TR256-1172		
HR METER	16585	HR	Odometer	90418	km
TIRE SIZE	385/95R25		YEAR	YR	

ENGINE : MODEL		S/N
Oil leakage	<input checked="" type="radio"/> FAIR · Attn	
Blow-By	<input checked="" type="radio"/> FAIR · Attn	A LITTLE · MIDDLE · SEVERE
Sound	<input checked="" type="radio"/> FAIR · Attn	
Oil	<input checked="" type="radio"/> FAIR · Attn	
Exhaust Color	<input checked="" type="radio"/> FAIR · Attn	
OPERATION PUMP		
Sound	<input checked="" type="radio"/> FAIR · Attn	
Oil leakage	<input checked="" type="radio"/> FAIR · Attn	
Power	<input checked="" type="radio"/> FAIR · Attn	
COOLING SYSTEM		
Radiator	<input checked="" type="radio"/> FAIR · Attn	
Oil Cooler	<input checked="" type="radio"/> FAIR · Attn	
OPERATING SYSTEM		
Computer	<input checked="" type="radio"/> OK · NG	
Swing	<input checked="" type="radio"/> FAIR · Attn	
Travel	<input checked="" type="radio"/> FAIR · Attn	
TRANSMISSION		
Transmission	<input checked="" type="radio"/> FAIR · Attn	
No. OF GEARS	4 GEARS	
4WD	<input checked="" type="radio"/> 4WD · 6WD	
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN · <input checked="" type="radio"/> FAIR · DIRTY	
Operator's Seat	<input checked="" type="radio"/> FAIR · Attn	
Glasses	<input checked="" type="radio"/> FAIR · Attn	
AirCon	<input checked="" type="radio"/> A/C · H/C · H only · C only · None	
COMMENT		

BOOM	
No. of Section	4 SECTIONS
CRACK/ENFORCEMENT	<input checked="" type="radio"/> FAIR · Attn
DERRICKING CYL.	<input checked="" type="radio"/> FAIR · Attn
EXTENSION CYL.	<input checked="" type="radio"/> FAIR · Attn
JIB	<input checked="" type="radio"/> YES · NO
JIB TYPE	STD · <input checked="" type="radio"/> PWR
MAIN & SUB WIRE	<input checked="" type="radio"/> YES · NO
FREE FALL	YES · <input checked="" type="radio"/> NO
HOOK	25t, BALL
UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4
TIRE WEAR	<input checked="" type="radio"/> FAIR · WORN · UNEVEN WEAR
COMMENT	
OUTRIGGERS	
OUTRIGGERS	<input checked="" type="radio"/> X · H
OUTRIGGERS COND.	<input checked="" type="radio"/> FAIR · Attn
Oil leakage (JACK CYL.)	FRONT L · R REAR L · R
Oil leakage (SLIDE CYL.)	FRONT L · R REAR L · R
COMMENT	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。