

INSPECTION SHEET 検品書  
BULLDOZER ブルドーザー

INSPECTION DATE	2026/6/12	MAKE	MITSUBISHI	MODEL	BD2G
SERIAL	2B101425		STAMP	2B101425	
HR METER	2889	HR	SHOE	500LGP	YEAR YR
BLADE	STRAIGHT / ST/TILT / PAT / ANGLE / OTHER		CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE	

<b>ENGINE : MODEL</b>		<b>S/N</b>	82661
Oil leakage	FAIR · <input checked="" type="radio"/> Attn	にじみ、油汚れあり OIL OozING, OIL STAINS	
Blow-By	FAIR · Attn	A LITTLE · MIDDLE · SEVERE	
Sound	FAIR · Attn		
Oil	FAIR · Attn		
Exhaust Color	FAIR · Attn		
US EPA	YES · <input checked="" type="radio"/> NO		
<b>OPERATION PUMP</b>			
Sound	FAIR · Attn		
Oil leakage	FAIR · Attn		
Power	FAIR · Attn		
<b>COOLING SYSTEM</b>			
Radiator	FAIR · Attn		
Oil Cooler	FAIR · Attn		
<b>TRANSMISSION &amp; TRAVEL</b>			
T/M TYPE	PS · <input checked="" type="radio"/> DD	DIFF. STEERING	YES · <input checked="" type="radio"/> NO
Transmission	FAIR · Attn		
Travel	FAIR · <input checked="" type="radio"/> Attn	右足切れづらい RIGHT TRACK: HARD TO MOVE	
<b>INTERIOR See Photos. 写真参照</b>			
INTERIOR COND.	CLEAN · <input checked="" type="radio"/> FAIR · <input type="radio"/> DIRTY		
Operator's Seat	FAIR · Attn		
Glasses	FAIR · Attn		
AirCon	A/C · H/C · H only · C only · <input checked="" type="radio"/> None		
<b>BLADE &amp; CYLINDERS</b>			
BLADE	FAIR · Attn		
CYLD.(R)	FAIR · Attn		
CYLD.(L)	FAIR · Attn		
TILT CYLD	FAIR · Attn		
ANGLE CYLD	FAIR · Attn		

<b>UNDERCARRIAGE See Photos. 写真参照</b>			
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			1
<b>COMMENT</b>			
Ripper	MULTI · S/S	Shanks	PCS
Ripper CYLD.	FAIR · Attn		
<b>COMMENT</b>			
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			2

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.  
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。