

INSPECTION SHEET 検品書
ROUGH TERRAIN CRANE ラフタークレーン

INSPECTION DATE	2026/4/2	MAKE	KATO	MODEL	KR-65H
SERIAL No.	PLATE :	0310129		STAMP :	KRC002-0129
HR METER	19909	HR	Odometer	134172	km
TIRE SIZE	505/95R25		YEAR	YR	

ENGINE : MODEL S/N

Oil leakage	FAIR	<input checked="" type="radio"/> Attn	油漏れあり OIL LEAKING
Blow-By	FAIR	<input checked="" type="radio"/> Attn	A LITTLE <input checked="" type="radio"/> MIDDLE <input type="radio"/> SEVERE
Sound	FAIR	<input type="radio"/> Attn	
Oil	FAIR	<input type="radio"/> Attn	
Exhaust Color	FAIR	<input type="radio"/> Attn	

OPERATION PUMP

Sound	FAIR	<input type="radio"/> Attn	
Oil leakage	FAIR	<input type="radio"/> Attn	
Power	FAIR	<input type="radio"/> Attn	

COOLING SYSTEM

Radiator	FAIR	<input type="radio"/> Attn	
Oil Cooler	FAIR	<input type="radio"/> Attn	

OPERATING SYSTEM

Computer	OK	<input type="radio"/> NG	
Swing	FAIR	<input type="radio"/> Attn	
Travel	FAIR	<input type="radio"/> Attn	

TRANSMISSION

Transmission	FAIR	<input checked="" type="radio"/> Attn	にじみあり OIL OozING
No. OF GEARS	4	GEARS	
4WD	<input checked="" type="radio"/> 4WD	<input type="radio"/> 6WD	

INTERIOR See Photos. 写真参照

INTERIOR COND.	CLEAN	<input checked="" type="radio"/> FAIR <input type="radio"/> DIRTY	
Operator's Seat	FAIR	<input type="radio"/> Attn	
Glasses	FAIR	<input type="radio"/> Attn	
AirCon	<input checked="" type="radio"/> A/C	<input type="radio"/> H/C <input type="radio"/> H only <input type="radio"/> C only <input type="radio"/> None	

COMMENT

A/C異音あり A/C: NOISES

BOOM

No. of Section	6	SECTIONS	
CRACK/ENFORCEMENT	FAIR	<input type="radio"/> Attn	
DERRICKING CYL.	FAIR	<input type="radio"/> Attn	
EXTENSION CYL.	FAIR	<input type="radio"/> Attn	
JIB	YES	<input type="radio"/> NO	
JIB TYPE	STD	<input type="radio"/> PWR	
MAIN & SUB WIRE	YES	<input type="radio"/> NO	
FREE FALL	YES	<input checked="" type="radio"/> NO	
HOOK	65t, 34t, BALL		

UNDERCARRIAGE : See Photos. 写真参照

RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4
TIRE WEAR	<input checked="" type="radio"/> FAIR <input type="radio"/> WORN <input type="radio"/> UNEVEN WEAR

COMMENT

OUTRIGGERS

OUTRIGGERS	X	<input checked="" type="radio"/> H	
OUTRIGGERS COND.	FAIR	<input type="radio"/> Attn	
Oil leakage (JACK CYL.)	FRONT	L <input type="radio"/> R	REAR L <input type="radio"/> R
Oil leakage (SLIDE CYL.)	FRONT	L <input type="radio"/> R	REAR L <input type="radio"/> R

COMMENT

ロータリージョイント油漏れあり ROTARY JOINT: OIL LEAKING

RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4
--	---

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。