INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2026/3/30	MAKE	KOMATSU	MODEL	PC350-8
SERIAL	63206			STAMP	KMTPC191K02063206
HR METER	11720 HR			YEAR	YR
CAB/CNP	(ROPS CAB) / CAB / ROPS CNP / CNP / NONE			SHOE	600G

ENGINE : MODEL S/N		
Oil leakage	FAIR ・(Attn)	*1
Blow-By	(FAIR)・ Attn	A LITTLE・ MIDDLE・ SEVERE
Sound	(FAIR)・ Attn	
Oil	(FAIR)・ Attn	
Exhaust Color	(FAIR)・ Attn	
US EPA	YES ・(NO)	
MAIN PUMP		
Sound	(FAIR)・ Attn	
Oil leakage	(FAIR)・ Attn	
Power	(FAIR)・ Attn	
COOLING SYSTEM		
Radiator	(FAIR)・ Attn	
Oil Cooler	(FAIR)・ Attn	
OPERATING SYSTEM		
Swing	(FAIR)・ Attn	ガタあり SWING: LOOSE
Travel	(FAIR)・ Attn	
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN ・ (FAIR) ・ DIRTY	
Operator's Seat	(FAIR)・ Attn	破れあり HUGE CUTS
Glasses	(FAIR)・ Attn	
AirCon	(A/C) ・ H/C ・ H only ・ C only ・ None	
BOOM / ARM / BKT		
Boom	(FAIR)・ Attn	
Boom Cylinder	FAIR ・(Attn)	左右にじみあり CYLINDERS: OIL OOZING
Arm	(FAIR)・ Attn	ガタあり LOOSE
Arm Cylinder	(FAIR)・ Attn	
ATTACHMENT	(FAIR)・ Attn	ガタあり LOOSE
BKT Cylinder	FAIR ・(Attn)	油漏れあり OIL LEAKING

UNDERCARRIAGE : See Photos. 写真参照		
RUST(5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2	
COMMENT		
BKT	(STD) / SLOPE / NARROW / SKELETON / OTHER( )	
Lever	LONG ・ (WRIST)	
Multi	(MULTI)・ 2 ・ NO	油漏れ小 OIL LEAKING
ARM-CRANE	YES ・(NO)	
BLADE	YES ・(NO)	
OFFSET	YES ・(NO)	
OFFSET Cylinder	FAIR ・ Attn	
Piping	(YES)・ NO	Breaker only ・ (Multi)
COMMENT		
ブーム下ホースひび割れあり		
SOME HOSE AROUND LOWER PART OF BOOM: MUCH CRACKED		
右サイドカバーラッチ破損あり RIGHT SIDE COVER LATCH: BROKEN		
オイルフィルター油漏れ小 OIL FILTER: OIL LEAKING		
*1 オイルパン周り油漏れあり AROUND OIL PAN: OIL LEAKING		
RUST of BODY(5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。