

INSPECTION SHEET 検品書
ROUGH TERRAIN CRANE ラフタークレーン

INSPECTION DATE	2026/4/3	MAKE	KATO	MODEL	KRM-13H-II
SERIAL No.	PLATE : 5811083	STAMP :		KRC008-1083	
HR METER	21009	HR	Odometer	130079	km
TIRE SIZE	275/80R22.5	YEAR	YR		

ENGINE : MODEL	S/N
Oil leakage	<input checked="" type="radio"/> FAIR · Attn
Blow-By	<input checked="" type="radio"/> FAIR · Attn A LITTLE · MIDDLE · SEVERE
Sound	<input checked="" type="radio"/> FAIR · Attn
Oil	<input checked="" type="radio"/> FAIR · Attn
Exhaust Color	<input checked="" type="radio"/> FAIR · Attn
OPERATION PUMP	
Sound	<input checked="" type="radio"/> FAIR · Attn
Oil leakage	<input checked="" type="radio"/> FAIR · Attn
Power	<input checked="" type="radio"/> FAIR · Attn
COOLING SYSTEM	
Radiator	<input checked="" type="radio"/> FAIR · Attn
Oil Cooler	<input checked="" type="radio"/> FAIR · Attn
OPERATING SYSTEM	
Computer	<input checked="" type="radio"/> OK · NG
Swing	<input checked="" type="radio"/> FAIR · Attn スイベル油漏れあり SWIVEL: OIL LEAKING
Travel	<input checked="" type="radio"/> FAIR · Attn
TRANSMISSION	
Transmission	<input checked="" type="radio"/> FAIR · Attn
No. OF GEARS	4 GEARS
4WD	<input checked="" type="radio"/> 4WD · 6WD
INTERIOR See Photos. 写真参照	
INTERIOR COND.	CLEAN · <input checked="" type="radio"/> FAIR · DIRTY
Operator's Seat	<input checked="" type="radio"/> FAIR · Attn
Glasses	<input checked="" type="radio"/> FAIR · Attn
AirCon	<input checked="" type="radio"/> A/C · H/C · H only · C only · None
COMMENT	

BOOM	
No. of Section	6 SECTIONS
CRACK/ENFORCEMENT	<input checked="" type="radio"/> FAIR · Attn
DERRICKING CYL.	<input checked="" type="radio"/> FAIR · Attn
EXTENSION CYL.	<input checked="" type="radio"/> FAIR · Attn
JIB	<input checked="" type="radio"/> YES · NO
JIB TYPE	STD · <input checked="" type="radio"/> PWR
MAIN & SUB WIRE	<input checked="" type="radio"/> YES · NO
FREE FALL	YES · <input checked="" type="radio"/> NO
HOOK	13t, BALL
UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 2: CORRODED)	4
TIRE WEAR	FAIR · WORN <input checked="" type="radio"/> UNEVEN WEAR
COMMENT	
OUTRIGGERS	
OUTRIGGERS	X · <input checked="" type="radio"/> H
OUTRIGGERS COND.	<input checked="" type="radio"/> FAIR · Attn
Oil leakage (JACK CYL.)	FRONT L · R REAR L · R
Oil leakage (SLIDE CYL.)	FRONT L · R REAR L · R
COMMENT	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。