INSPECTION SHEET 検品書
DUMP TRUCK ダンプ

INSPECTION DATE	2026/3/30	CATEGORY	ON-ROAD DUMP ・ (OFF-ROAD DUMP)		
MAKE	KOMATSU		MODEL	HM300-5	
SERIAL	11080		STAMP	KMTHM015VKD011080	
HR METER	5486 HR		ODOMETER	31994 km	
TIRE SIZE	30/65R25		YEAR	YR	

ENGINE : MODEL 6D125E-7 S/N 866839		
Oil leakage	(FAIR) ・ Attn	
Blow-By	(FAIR) ・ Attn	A LITTLE ・ MIDDLE ・ SEVERE
Sound	(FAIR) ・ Attn	
Oil	(FAIR) ・ Attn	
Exhaust Color	(FAIR) ・ Attn	
US EPA	YES ・(NO)	

OPERATION PUMP		
Sound	(FAIR) ・ Attn	
Oil leakage	(FAIR) ・ Attn	
Power	(FAIR) ・ Attn	

COOLING SYSTEM		
Radiator	(FAIR) ・ Attn	
Oil Cooler	(FAIR) ・ Attn	

TRANSMISSION & TRAVEL				
T/M TYPE	(AT) ・ MT		No. OF GEARS	5 GEARS
Transmission	(FAIR) ・ Attn			
4WD	4WD ・(2WD)			
Travel	(FAIR) ・ Attn			
Articulate	(FAIR) ・ Attn			
FOOT BRAKE	(FAIR) ・ Attn			
PARKING BRAKE	(FAIR) ・ Attn			

INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN ・ (FAIR) ・ DIRTY	
Operator's Seat	(FAIR) ・ Attn	
Glasses	(FAIR) ・ Attn	
AirCon	(A/C) ・ H/C ・ H only ・ C only ・ None	

MAIN FRAME		
MAIN FLAME	(FAIR) ・ Attn	

VESSEL		
MAKE		
VESSEL	(FAIR) ・ Attn	
REAR GATE TYPE	NORMAL ・ L-GATE (FLAT)	
REAR GATE	FAIR ・ Attn	

UNDERCARRIAGE: See Photos. 写真参照		
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		4
TIRE WEAR	FAIR (・ WORN) ・ UNEVEN WEAR	

COMMENT

ROPS-CAB

付属品:プロテクター PROTECTOR AS SPARE

RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。