

**INSPECTION SHEET 検品書**  
**CRAWLER CRANE クローラクレーン**

INSPECTION DATE	2026/3/30	MAKE	NAGANO	MODEL	CX26-3
SERIAL No.	PLATE : CX2630069	STAMP		CX2630069	
HR METER	2263	HR	SHOE	300R	YEAR YR

<b>ENGINE : MODEL</b>		<b>S/N</b>
Oil leakage	<input checked="" type="radio"/> FAIR · Attn	
Blow-By	<input checked="" type="radio"/> FAIR · Attn	A LITTLE · MIDDLE · SEVERE
Sound	<input checked="" type="radio"/> FAIR · Attn	
Oil	<input checked="" type="radio"/> FAIR · Attn	
Exhaust Color	<input checked="" type="radio"/> FAIR · Attn	
<b>OPERATION PUMP</b>		
Sound	<input checked="" type="radio"/> FAIR · Attn	
Oil leakage	<input checked="" type="radio"/> FAIR · Attn	
Power	<input checked="" type="radio"/> FAIR · Attn	
<b>COOLING SYSTEM</b>		
Radiator	<input checked="" type="radio"/> FAIR · Attn	
Oil Cooler	<input checked="" type="radio"/> FAIR · Attn	
<b>OPERATING SYSTEM</b>		
Computer	<input checked="" type="radio"/> OK · NG	
Swing	<input checked="" type="radio"/> FAIR · Attn	
Travel	<input checked="" type="radio"/> FAIR · Attn	
<b>BOOM</b>		
MAIN BOOM		
BOOM TOTAL		
TOP SHEAVE	YES · <input checked="" type="radio"/> NO	
JIB		
TOWER		

<b>INTERIOR</b> See Photos. 写真参照	
INTERIOR COND.	CLEAN · <input checked="" type="radio"/> FAIR · DIRTY
Operator's Seat	<input checked="" type="radio"/> FAIR · Attn
Glasses	<input checked="" type="radio"/> FAIR · Attn
AirCon	A/C · H/C · H only · C only · <input checked="" type="radio"/> None
<b>UNDERCARRIAGE :</b> See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4
<b>COMMENT</b>	
WEIGHT	-
HOOK	2.6t
FREE FALL	YES · <input checked="" type="radio"/> NO
LIFTER	YES · <input checked="" type="radio"/> NO
<b>COMMENT</b>	
CNP	
BLADE	
3段ブーム 3-SECTION BOOM	
リペイントあり REPAINTED	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.  
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。