

INSPECTION SHEET 検品書
ROUGH TERRAIN CRANE ラフタークレーン

INSPECTION DATE	2026/4/3	MAKE	KATO	MODEL	KR-10H
SERIAL No.	PLATE :	2511243	STAMP :	KR100-1243	
HR METER	19060	HR	Odometer	76538	km
TIRE SIZE	11R22.5	YEAR	1994	YR	

ENGINE : MODEL		S/N
Oil leakage	<input type="radio"/> FAIR · <input type="radio"/> Attn	
Blow-By	<input type="radio"/> FAIR · <input type="radio"/> Attn	A LITTLE · MIDDLE · <input checked="" type="radio"/> SEVERE
Sound	<input type="radio"/> FAIR · <input type="radio"/> Attn	
Oil	<input type="radio"/> FAIR · <input type="radio"/> Attn	
Exhaust Color	<input type="radio"/> FAIR · <input type="radio"/> Attn	白煙あり WHITE FUMES
OPERATION PUMP		
Sound	<input type="radio"/> FAIR · <input type="radio"/> Attn	
Oil leakage	<input type="radio"/> FAIR · <input type="radio"/> Attn	
Power	<input type="radio"/> FAIR · <input type="radio"/> Attn	
COOLING SYSTEM		
Radiator	<input type="radio"/> FAIR · <input type="radio"/> Attn	
Oil Cooler	<input type="radio"/> FAIR · <input type="radio"/> Attn	
OPERATING SYSTEM		
Computer	<input checked="" type="radio"/> OK · <input type="radio"/> NG	*1
Swing	<input type="radio"/> FAIR · <input type="radio"/> Attn	
Travel	<input type="radio"/> FAIR · <input type="radio"/> Attn	
TRANSMISSION		
Transmission	<input type="radio"/> FAIR · <input type="radio"/> Attn	にじみあり OIL OOZING
No. OF GEARS	4 GEARS	
4WD	<input checked="" type="radio"/> 4WD · <input type="radio"/> 6WD	
INTERIOR See Photos. 写真参照		
INTERIOR COND.	<input type="radio"/> CLEAN · <input checked="" type="radio"/> FAIR · <input type="radio"/> DIRTY	
Operator's Seat	<input type="radio"/> FAIR · <input type="radio"/> Attn	
Glasses	<input type="radio"/> FAIR · <input type="radio"/> Attn	
AirCon	A/C · <input checked="" type="radio"/> H/C · <input type="radio"/> H only · <input type="radio"/> C only · <input type="radio"/> None	
COMMENT		

BOOM	
No. of Section	6 SECTIONS
CRACK/ENFORCEMENT	<input type="radio"/> FAIR · <input type="radio"/> Attn
DERRICKING CYL.	<input type="radio"/> FAIR · <input checked="" type="radio"/> Attn 油漏れあり OIL LEAKING
EXTENSION CYL.	<input type="radio"/> FAIR · <input checked="" type="radio"/> Attn 油漏れあり OIL LEAKING
JIB	YES · <input checked="" type="radio"/> NO
JIB TYPE	STD · <input type="radio"/> PWR
MAIN & SUB WIRE	<input checked="" type="radio"/> YES · <input type="radio"/> NO
FREE FALL	<input checked="" type="radio"/> YES · <input type="radio"/> NO
HOOK	10t, BALL
UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
TIRE WEAR	<input checked="" type="radio"/> FAIR · <input type="radio"/> WORN · <input type="radio"/> UNEVEN WEAR
COMMENT	
左右Rタイヤ亀裂あり REAR TIRES: CRACKED	
OUTRIGGERS	
OUTRIGGERS	X · <input checked="" type="radio"/> H
OUTRIGGERS COND.	<input type="radio"/> FAIR · <input type="radio"/> Attn
Oil leakage (JACK CYL.)	FRONT <input checked="" type="radio"/> L · <input checked="" type="radio"/> R REAR L · R
Oil leakage (SLIDE CYL.)	FRONT L · R REAR L · R
COMMENT	
補ウインチホース油漏れあり	
AUXILIARY HOISTING WINCH HOSE: OIL LEAKING	
*1 表示不良(画面焼け、映らない) MONITOR: MALFUNCTION TO DISPLAY	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
3	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。