

INSPECTION SHEET 検品書
ROUGH TERRAIN CRANE ラフタークレーン

INSPECTION DATE	2026/4/7	MAKE	KATO	MODEL	KRM-13H
SERIAL No.	PLATE : 5911129	STAMP : KR130-1129			
HR METER	21858	HR	Odometer	188491	km
TIRE SIZE	275/80R22.5	YEAR	2006	YR	

ENGINE : MODEL		S/N
Oil leakage	<input checked="" type="radio"/> FAIR · <input type="radio"/> Attn	
Blow-By	<input checked="" type="radio"/> FAIR · <input type="radio"/> Attn	A LITTLE · <input checked="" type="radio"/> MIDDLE · SEVERE
Sound	<input checked="" type="radio"/> FAIR · <input type="radio"/> Attn	
Oil	<input checked="" type="radio"/> FAIR · <input type="radio"/> Attn	
Exhaust Color	<input checked="" type="radio"/> FAIR · <input type="radio"/> Attn	
OPERATION PUMP		
Sound	<input checked="" type="radio"/> FAIR · <input type="radio"/> Attn	
Oil leakage	<input checked="" type="radio"/> FAIR · <input type="radio"/> Attn	油漏れあり OIL LEAKING
Power	<input checked="" type="radio"/> FAIR · <input type="radio"/> Attn	
COOLING SYSTEM		
Radiator	<input checked="" type="radio"/> FAIR · <input type="radio"/> Attn	
Oil Cooler	<input checked="" type="radio"/> FAIR · <input type="radio"/> Attn	
OPERATING SYSTEM		
Computer	<input checked="" type="radio"/> OK · <input type="radio"/> NG	
Swing	<input checked="" type="radio"/> FAIR · <input type="radio"/> Attn	
Travel	<input checked="" type="radio"/> FAIR · <input type="radio"/> Attn	
TRANSMISSION		
Transmission	<input checked="" type="radio"/> FAIR · <input type="radio"/> Attn	油漏れあり OIL LEAKING
No. OF GEARS	4 GEARS	
4WD	<input checked="" type="radio"/> 4WD · <input type="radio"/> 6WD	
INTERIOR See Photos. 写真参照		
INTERIOR COND.	<input checked="" type="radio"/> CLEAN · <input type="radio"/> FAIR · <input type="radio"/> DIRTY	
Operator's Seat	<input checked="" type="radio"/> FAIR · <input type="radio"/> Attn	
Glasses	<input checked="" type="radio"/> FAIR · <input type="radio"/> Attn	
AirCon	<input checked="" type="radio"/> A/C · <input type="radio"/> H/C · <input type="radio"/> H only · <input type="radio"/> C only · <input type="radio"/> None	
COMMENT		

BOOM			
No. of Section	6 SECTIONS		
CRACK/ENFORCEMENT	<input checked="" type="radio"/> FAIR · <input type="radio"/> Attn		
DERRICKING CYL.	<input checked="" type="radio"/> FAIR · <input type="radio"/> Attn		
EXTENSION CYL.	<input checked="" type="radio"/> FAIR · <input type="radio"/> Attn		
JIB	<input checked="" type="radio"/> YES · <input type="radio"/> NO		
JIB TYPE	STD · <input checked="" type="radio"/> PWR		
MAIN & SUB WIRE	<input checked="" type="radio"/> YES · <input type="radio"/> NO		
FREE FALL	YES · <input checked="" type="radio"/> NO		
HOOK	13t, BALL		
UNDERCARRIAGE : See Photos. 写真参照			
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			4
TIRE WEAR <input checked="" type="radio"/> FAIR · <input type="radio"/> WORN · <input type="radio"/> UNEVEN WEAR			
COMMENT			
リアステアリングシリンダー油漏れあり			
REAR STEERING CYLINDER: OIL LEAKING			
OUTRIGGERS			
OUTRIGGERS	X · <input checked="" type="radio"/> H		
OUTRIGGERS COND.	<input checked="" type="radio"/> FAIR · <input type="radio"/> Attn		
Oil leakage (JACK CYL.)	FRONT	L · R	REAR L · R
Oil leakage (SLIDE CYL.)	FRONT	L · R	REAR L · R
COMMENT			
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			4

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。