

INSPECTION SHEET 検品書
BULLDOZER ブルドーザー

INSPECTION DATE	2026/3/31	MAKE	MITSUBISHI	MODEL	BD2H
SERIAL	HB650157			STAMP	2B650157
HR METER	3564	HR	SHOE	500R	YEAR YR
BLADE	STRAIGHT / ST/TILT / PAT / ANGLE / OTHER			CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE

ENGINE : MODEL		S/N	29631
Oil leakage	<input type="radio"/> FAIR · Attn		
Blow-By	<input type="radio"/> FAIR · Attn	A LITTLE · MIDDLE · SEVERE	
Sound	<input type="radio"/> FAIR · Attn		
Oil	<input type="radio"/> FAIR · Attn		
Exhaust Color	<input type="radio"/> FAIR · Attn		
US EPA	YES · <input checked="" type="radio"/> NO		
OPERATION PUMP			
Sound	<input type="radio"/> FAIR · Attn		
Oil leakage	<input type="radio"/> FAIR · Attn		
Power	<input type="radio"/> FAIR · Attn		
COOLING SYSTEM			
Radiator	<input type="radio"/> FAIR · Attn		
Oil Cooler	<input type="radio"/> FAIR · Attn		
TRANSMISSION & TRAVEL			
T/M TYPE	<input checked="" type="radio"/> PS · DD	DIFF. STEERING	YES · <input checked="" type="radio"/> NO
Transmission	<input type="radio"/> FAIR · Attn		
Travel	<input type="radio"/> FAIR · Attn	右レバー持ち手欠 RIGHT LEVER GRIP: MISSING	
INTERIOR See Photos. 写真参照			
INTERIOR COND.	CLEAN · <input checked="" type="radio"/> FAIR ·	DIRTY	
Operator's Seat	<input type="radio"/> FAIR · Attn		
Glasses	<input type="radio"/> FAIR · Attn		
AirCon	A/C · H/C · H only · C only · <input checked="" type="radio"/> None		
BLADE & CYLINDERS			
BLADE	<input type="radio"/> FAIR · Attn		
CYLD.(R)	<input type="radio"/> FAIR · Attn		
CYLD.(L)	<input type="radio"/> FAIR · Attn		
TILT CYLD	<input type="radio"/> FAIR · Attn		
ANGLE CYLD	<input type="radio"/> FAIR · Attn		

UNDERCARRIAGE See Photos. 写真参照			
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			3
COMMENT			
<div style="border: 1px solid black; padding: 5px; margin-bottom: 5px;"> Ripper MULTI · S/S Shanks PCS </div> <div style="border: 1px solid black; padding: 5px; margin-bottom: 5px;"> Ripper CYLD. FAIR · Attn </div>			
COMMENT			
メーター内結露あり(水が入っている)			
INSIDE OF METER COVER: CONDENSED			
リペイントあり REPAINTED			
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			2

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。