INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2026/3/13	MAKE	KOBELCO	MODEL	SK70SRD-2
SERIAL	YT05-15688		STAMP	YT05-15688	
HR METER	8856 HR		YEAR	YR	
CAB/CNP	ROPS CAB / (CAB) / ROPS CNP / CNP / NONE		SHOE	450FLAT	

ENGINE : MODEL 4LE2 S/N		
Oil leakage	FAIR · (Attn)	油汚れあり OIL STAINS
Blow-By	(FAIR) · Attn	A LITTLE · MIDDLE · SEVERE
Sound	(FAIR) · Attn	
Oil	(FAIR) · Attn	
Exhaust Color	(FAIR) · Attn	
US EPA	(YES) · NO	
MAIN PUMP		
Sound	(FAIR) · Attn	
Oil leakage	(FAIR) · Attn	
Power	(FAIR) · Attn	
COOLING SYSTEM		
Radiator	(FAIR) · Attn	
Oil Cooler	(FAIR) · Attn	
OPERATING SYSTEM		
Swing	(FAIR) · Attn	
Travel	(FAIR) · Attn	
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN · (FAIR) · DIRTY	
Operator's Seat	(FAIR) · Attn	
Glasses	FAIR · (Attn)	*1
AirCon	(A/C) · H/C · H only · C only · None	
BOOM / ARM / BKT		
Boom	FAIR · (Attn)	補強跡あり REINFORCED
Boom Cylinder	(FAIR) · Attn	
Arm	(FAIR) · Attn	
Arm Cylinder	(FAIR) · Attn	
ATTACHMENT	FAIR · Attn	
BKT Cylinder	(FAIR) · Attn	

UNDERCARRIAGE : See Photos. 写真参照			
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4		
COMMENT			
BKT	STD / SLOPE / NARROW / SKELETON / OTHER( )		
Lever	LONG · (WRIST)		
Multi	(MULTI) · 2 · NO		
ARM-CRANE	YES · (NO)		
BLADE	(YES) · NO		
OFFSET	YES · (NO)		
OFFSET Cylinder	FAIR · Attn		
Piping	(YES) · NO	Breaker only · Multi 4 *2	

COMMENT

ボディヘコミ多数あり BODY: DEFORMED

A/Cベルト欠 A/C: NO BELT

アタッチメントなし WITHOUT ATTACHMENT

*1 ドアガラス:アクリル加工あり DOOR GLASSES: ACRYLIC BOARDS

*2 油圧ホース欠、右配管1本欠 HOSES: MISSING, SOME RIGHT PIPE: MISSING (ACTUALLY 5-PIPING)

RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。