

INSPECTION SHEET 検品書  
EXCAVATOR バックホー

INSPECTION DATE	2026/4/9	MAKE	HITACHI	MODEL	ZX135USOS-3
SERIAL	HCM1RK00T00094971		STAMP	HCM1RK00T00094971	
HR METER	7963	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	500G	

**ENGINE : MODEL** 4JJ1 **S/N** 167070

Oil leakage	FAIR	Attn	
Blow-By	FAIR	Attn	A LITTLE · MIDDLE · SEVERE
Sound	FAIR	Attn	
Oil	FAIR	Attn	
Exhaust Color	FAIR	Attn	
US EPA	YES	NO	

**MAIN PUMP**

Sound	FAIR	Attn	
Oil leakage	FAIR	Attn	
Power	FAIR	Attn	

**COOLING SYSTEM**

Radiator	FAIR	Attn	
Oil Cooler	FAIR	Attn	

**OPERATING SYSTEM**

Swing	FAIR	Attn	ガタあり SWING: LOOSE
Travel	FAIR	Attn	

**INTERIOR** See Photos. 写真参照

INTERIOR COND.	CLEAN	FAIR	DIRTY
Operator's Seat	FAIR	Attn	
Glasses	FAIR	Attn	
AirCon	A/C	H/C	H only · C only · None

**BOOM / ARM / BKT**

Boom	FAIR	Attn	
Boom Cylinder	FAIR	Attn	
Arm	FAIR	Attn	
Arm Cylinder	FAIR	Attn	
ATTACHMENT	FAIR	Attn	
BKT Cylinder	FAIR	Attn	

**UNDERCARRIAGE :** See Photos. 写真参照

RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
<b>COMMENT</b>	
BKT	STD / SLOPE / NARROW / SKELETON / OTHER ( )
Lever	LONG · WRIST
Multi	MULTI · 2 · NO
ARM-CRANE	YES · NO
BLADE	YES · NO
OFFSET	YES · NO
OFFSET Cylinder	FAIR · Attn
Piping	YES · NO Breaker only · Multi

**COMMENT**

ウエイト周りリペイントあり  
COUNTERWEIGHT & AROUND COUNTERWEIGHT: REPAINTED

RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 4

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.  
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。