

INSPECTION SHEET 検品書  
CARRY DUMP キャリーダンプ

INSPECTION DATE	2026/4/7	MAKE	IHI	MODEL	IC120
SERIAL	CB003141		STAMP	CB003141	
HR METER	2570	HR	Odometer	km	YEAR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	750R	TIRE
					2014 YR

<b>ENGINE : MODEL</b> QSL9		<b>S/N</b> 73656486	
Oil leakage	<input checked="" type="radio"/> FAIR	Attn	
Blow-By	<input checked="" type="radio"/> FAIR	A LITTLE · MIDDLE · SEVERE	
Sound	<input checked="" type="radio"/> FAIR	Attn	
Oil	<input checked="" type="radio"/> FAIR	Attn	
Exhaust Color	<input checked="" type="radio"/> FAIR	Attn	
US EPA	YES	<input checked="" type="radio"/> NO	
<b>OPERATION PUMP</b>			
Sound	<input checked="" type="radio"/> FAIR	Attn	
Oil leakage	<input checked="" type="radio"/> FAIR	Attn	
Power	<input checked="" type="radio"/> FAIR	Attn	
<b>COOLING SYSTEM</b>			
Radiator	<input checked="" type="radio"/> FAIR	Attn	
Oil Cooler	<input checked="" type="radio"/> FAIR	Attn	
<b>TRANSMISSION &amp; TRAVEL</b>			
T/M TYPE	<input checked="" type="radio"/> PS	<input type="radio"/> DD	No. OF GEARS 2 GEARS
Transmission	<input checked="" type="radio"/> FAIR	Attn	
Travel	<input checked="" type="radio"/> FAIR	Attn	
Swing	<input type="radio"/> FAIR	Attn	
Articulate	<input type="radio"/> FAIR	Attn	
FOOT BRAKE	<input type="radio"/> FAIR	Attn	
PARKING BRAKE	<input checked="" type="radio"/> FAIR	Attn	
<b>INTERIOR</b> See Photos. 写真参照			
INTERIOR COND.	<input type="radio"/> CLEAN	<input checked="" type="radio"/> FAIR	<input type="radio"/> DIRTY
Operator's Seat	<input checked="" type="radio"/> FAIR	Attn	
Glasses	<input checked="" type="radio"/> FAIR	Attn	
AirCon	<input checked="" type="radio"/> A/C	<input type="radio"/> H/C	<input type="radio"/> H only · <input type="radio"/> C only · <input type="radio"/> None

<b>MAIN FRAME</b>	
MAIN FLAME	<input checked="" type="radio"/> FAIR · Attn
<b>VESSEL</b>	
VESSEL	<input checked="" type="radio"/> FAIR · Attn
REAR GATE TYPE	<input type="radio"/> NORMAL · <input type="radio"/> L-GATE (FLAT)
REAR GATE	<input checked="" type="radio"/> FAIR · Attn
<b>UNDERCARRIAGE:</b> See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
TIRE WEAR	<input type="radio"/> FAIR · <input type="radio"/> WORN · <input type="radio"/> UNEVEN WEAR
<b>COMMENT</b>	
<div style="border-bottom: 1px dotted black; margin-bottom: 5px;"></div> <div style="border-bottom: 1px dotted black; margin-bottom: 5px;"></div> <div style="border-bottom: 1px dotted black; margin-bottom: 5px;"></div> <div style="border-bottom: 1px dotted black; margin-bottom: 5px;"></div> <div style="border-bottom: 1px dotted black; margin-bottom: 5px;"></div> <div style="border-bottom: 1px dotted black; margin-bottom: 5px;"></div> <div style="border-bottom: 1px dotted black; margin-bottom: 5px;"></div> <div style="border-bottom: 1px dotted black; margin-bottom: 5px;"></div> <div style="border-bottom: 1px dotted black; margin-bottom: 5px;"></div> <div style="border-bottom: 1px dotted black; margin-bottom: 5px;"></div> <div style="border-bottom: 1px dotted black; margin-bottom: 5px;"></div> <div style="border-bottom: 1px dotted black; margin-bottom: 5px;"></div> <div style="border-bottom: 1px dotted black; margin-bottom: 5px;"></div> <div style="border-bottom: 1px dotted black; margin-bottom: 5px;"></div> <div style="border-bottom: 1px dotted black; margin-bottom: 5px;"></div> <div style="border-bottom: 1px dotted black; margin-bottom: 5px;"></div> <div style="border-bottom: 1px dotted black; margin-bottom: 5px;"></div> <div style="border-bottom: 1px dotted black; margin-bottom: 5px;"></div> <div style="border-bottom: 1px dotted black; margin-bottom: 5px;"></div> <div style="border-bottom: 1px dotted black; margin-bottom: 5px;"></div> <div style="border-bottom: 1px dotted black; margin-bottom: 5px;"></div>	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.  
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。