

INSPECTION SHEET 検品書
BULLDOZER ブルドーザー

INSPECTION DATE	2026/4/2	MAKE	CAT	MODEL	D6TLGP-19A
SERIAL	CAT00D6TTSGZ00512		STAMP	CAT00D6TTSGZ00512	
HR METER	8523	HR	SHOE	1000LGP	YEAR YR
BLADE	STRAIGHT (ST/TILT) PAT / ANGLE / OTHER		CAB/CNP	(ROPS CAB) / CAB / ROPS CNP / CNP / NONE	

<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 30%;">ENGINE : MODEL</td> <td style="width: 70%;">S/N</td> </tr> <tr> <td>Oil leakage</td> <td>(FAIR) · Attn</td> </tr> <tr> <td>Blow-By</td> <td>(FAIR) · Attn A LITTLE · MIDDLE · SEVERE</td> </tr> <tr> <td>Sound</td> <td>(FAIR) · Attn</td> </tr> <tr> <td>Oil</td> <td>(FAIR) · Attn</td> </tr> <tr> <td>Exhaust Color</td> <td>(FAIR) · Attn</td> </tr> <tr> <td>US EPA</td> <td>(YES) · NO</td> </tr> <tr> <td colspan="2">OPERATION PUMP</td> </tr> <tr> <td>Sound</td> <td>(FAIR) · Attn</td> </tr> <tr> <td>Oil leakage</td> <td>(FAIR) · Attn</td> </tr> <tr> <td>Power</td> <td>(FAIR) · Attn</td> </tr> <tr> <td colspan="2">COOLING SYSTEM</td> </tr> <tr> <td>Radiator</td> <td>(FAIR) · Attn</td> </tr> <tr> <td>Oil Cooler</td> <td>(FAIR) · Attn</td> </tr> <tr> <td colspan="2">TRANSMISSION & TRAVEL</td> </tr> <tr> <td>T/M TYPE</td> <td>(PS) · DD DIFF. STEERING (YES) · NO</td> </tr> <tr> <td>Transmission</td> <td>(FAIR) · Attn</td> </tr> <tr> <td>Travel</td> <td>(FAIR) · Attn</td> </tr> <tr> <td colspan="2">INTERIOR See Photos. 写真参照</td> </tr> <tr> <td>INTERIOR COND.</td> <td>(CLEAN) FAIR · DIRTY</td> </tr> <tr> <td>Operator's Seat</td> <td>(FAIR) · Attn</td> </tr> <tr> <td>Glasses</td> <td>(FAIR) · Attn</td> </tr> <tr> <td>AirCon</td> <td>(A/C) · H/C · H only · C only · None</td> </tr> <tr> <td colspan="2">BLADE & CYLINDERS</td> </tr> <tr> <td>BLADE</td> <td>(FAIR) · Attn</td> </tr> <tr> <td>CYLD.(R)</td> <td>(FAIR) · Attn</td> </tr> <tr> <td>CYLD.(L)</td> <td>(FAIR) · Attn</td> </tr> <tr> <td>TILT CYLD</td> <td>(FAIR) · Attn</td> </tr> <tr> <td>ANGLE CYLD</td> <td>FAIR · Attn</td> </tr> </table>	ENGINE : MODEL	S/N	Oil leakage	(FAIR) · Attn	Blow-By	(FAIR) · Attn A LITTLE · MIDDLE · SEVERE	Sound	(FAIR) · Attn	Oil	(FAIR) · Attn	Exhaust Color	(FAIR) · Attn	US EPA	(YES) · NO	OPERATION PUMP		Sound	(FAIR) · Attn	Oil leakage	(FAIR) · Attn	Power	(FAIR) · Attn	COOLING SYSTEM		Radiator	(FAIR) · Attn	Oil Cooler	(FAIR) · Attn	TRANSMISSION & TRAVEL		T/M TYPE	(PS) · DD DIFF. STEERING (YES) · NO	Transmission	(FAIR) · Attn	Travel	(FAIR) · Attn	INTERIOR See Photos. 写真参照		INTERIOR COND.	(CLEAN) FAIR · DIRTY	Operator's Seat	(FAIR) · Attn	Glasses	(FAIR) · Attn	AirCon	(A/C) · H/C · H only · C only · None	BLADE & CYLINDERS		BLADE	(FAIR) · Attn	CYLD.(R)	(FAIR) · Attn	CYLD.(L)	(FAIR) · Attn	TILT CYLD	(FAIR) · Attn	ANGLE CYLD	FAIR · Attn	<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="2">UNDERCARRIAGE See Photos. 写真参照</td> </tr> <tr> <td>RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)</td> <td style="text-align: center;">4</td> </tr> <tr> <td colspan="2">COMMENT</td> </tr> <tr> <td colspan="2" style="height: 100px;"> <div style="border: 1px solid black; padding: 5px; margin-bottom: 5px;"> Ripper MULTI · S/S Shanks PCS Ripper CYLD. FAIR · Attn </div> </td> </tr> <tr> <td colspan="2">COMMENT</td> </tr> <tr> <td colspan="2" style="height: 100px;"> プッシュアーム固定ボルト2本欠(ブレードリンクボルト留め) 2 PUSH ARM LOCK BOLT: MISSING (FIXING WITH BLADE LINK BOLTS) </td> </tr> <tr> <td colspan="2">RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)</td> </tr> <tr> <td></td> <td style="text-align: center;">4</td> </tr> </table>	UNDERCARRIAGE See Photos. 写真参照		RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4	COMMENT		<div style="border: 1px solid black; padding: 5px; margin-bottom: 5px;"> Ripper MULTI · S/S Shanks PCS Ripper CYLD. FAIR · Attn </div>		COMMENT		プッシュアーム固定ボルト2本欠(ブレードリンクボルト留め) 2 PUSH ARM LOCK BOLT: MISSING (FIXING WITH BLADE LINK BOLTS)		RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			4
ENGINE : MODEL	S/N																																																																										
Oil leakage	(FAIR) · Attn																																																																										
Blow-By	(FAIR) · Attn A LITTLE · MIDDLE · SEVERE																																																																										
Sound	(FAIR) · Attn																																																																										
Oil	(FAIR) · Attn																																																																										
Exhaust Color	(FAIR) · Attn																																																																										
US EPA	(YES) · NO																																																																										
OPERATION PUMP																																																																											
Sound	(FAIR) · Attn																																																																										
Oil leakage	(FAIR) · Attn																																																																										
Power	(FAIR) · Attn																																																																										
COOLING SYSTEM																																																																											
Radiator	(FAIR) · Attn																																																																										
Oil Cooler	(FAIR) · Attn																																																																										
TRANSMISSION & TRAVEL																																																																											
T/M TYPE	(PS) · DD DIFF. STEERING (YES) · NO																																																																										
Transmission	(FAIR) · Attn																																																																										
Travel	(FAIR) · Attn																																																																										
INTERIOR See Photos. 写真参照																																																																											
INTERIOR COND.	(CLEAN) FAIR · DIRTY																																																																										
Operator's Seat	(FAIR) · Attn																																																																										
Glasses	(FAIR) · Attn																																																																										
AirCon	(A/C) · H/C · H only · C only · None																																																																										
BLADE & CYLINDERS																																																																											
BLADE	(FAIR) · Attn																																																																										
CYLD.(R)	(FAIR) · Attn																																																																										
CYLD.(L)	(FAIR) · Attn																																																																										
TILT CYLD	(FAIR) · Attn																																																																										
ANGLE CYLD	FAIR · Attn																																																																										
UNDERCARRIAGE See Photos. 写真参照																																																																											
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4																																																																										
COMMENT																																																																											
<div style="border: 1px solid black; padding: 5px; margin-bottom: 5px;"> Ripper MULTI · S/S Shanks PCS Ripper CYLD. FAIR · Attn </div>																																																																											
COMMENT																																																																											
プッシュアーム固定ボルト2本欠(ブレードリンクボルト留め) 2 PUSH ARM LOCK BOLT: MISSING (FIXING WITH BLADE LINK BOLTS)																																																																											
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)																																																																											
	4																																																																										

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
 この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。