

**INSPECTION SHEET 検品書**  
**CRAWLER CRANE クローラクレーン**

INSPECTION DATE	2026/4/3	MAKE	MAEDA	MODEL	LC1385M-8
SERIAL No.	PLATE : 8015	STAMP		KMTPC189P01024546	
HR METER	7305	HR	SHOE	500G PADS	YEAR 2009 YR

<b>ENGINE : MODEL 4D95LE-5 S/N 509292</b>	
Oil leakage	<input checked="" type="radio"/> FAIR · Attn
Blow-By	<input checked="" type="radio"/> FAIR · Attn A LITTLE · MIDDLE · SEVERE
Sound	<input checked="" type="radio"/> FAIR · Attn
Oil	<input checked="" type="radio"/> FAIR · Attn
Exhaust Color	<input checked="" type="radio"/> FAIR · Attn
<b>OPERATION PUMP</b>	
Sound	<input checked="" type="radio"/> FAIR · Attn
Oil leakage	<input checked="" type="radio"/> FAIR · Attn
Power	<input checked="" type="radio"/> FAIR · Attn
<b>COOLING SYSTEM</b>	
Radiator	<input checked="" type="radio"/> FAIR · Attn
Oil Cooler	<input checked="" type="radio"/> FAIR · Attn
<b>OPERATING SYSTEM</b>	
Computer	<input checked="" type="radio"/> OK · NG
Swing	<input checked="" type="radio"/> FAIR · Attn
Travel	<input checked="" type="radio"/> FAIR · Attn
<b>BOOM</b>	
MAIN BOOM	
BOOM TOTAL	
TOP SHEAVE	YES · <input checked="" type="radio"/> NO
JIB	
TOWER	

<b>INTERIOR See Photos. 写真参照</b>	
INTERIOR COND.	CLEAN · <input checked="" type="radio"/> FAIR · DIRTY
Operator's Seat	<input checked="" type="radio"/> FAIR · Attn 破れあり TORN
Glasses	<input checked="" type="radio"/> FAIR · Attn
AirCon	<input checked="" type="radio"/> A/C · H/C · H only · C only · None
<b>UNDERCARRIAGE : See Photos. 写真参照</b>	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4
<b>COMMENT</b>	
WEIGHT	-
HOOK	4.9t
FREE FALL	YES · <input checked="" type="radio"/> NO
LIFTER	YES · <input checked="" type="radio"/> NO
<b>COMMENT</b>	
CAB	
EPA: YES	
5段ブーム 5-SECTION BOOM	
ブーム伏せ: 非常ボタン押さないといけない	
GOING DOWN BOOM: NEED TO OPERATE IN THE EMERGENCY MODE	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.  
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。