

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2026/4/8	MAKE	KOBELCO	MODEL	SK135SR-2
SERIAL	YY06-18713		STAMP	YY06-18713	
HR METER	7032	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	500G	

ENGINE : MODEL D04FR **S/N** 013659

Oil leakage	FAIR	Attn	
Blow-By	FAIR	Attn	A LITTLE · MIDDLE · SEVERE
Sound	FAIR	Attn	
Oil	FAIR	Attn	
Exhaust Color	FAIR	Attn	
US EPA	YES	NO	

MAIN PUMP

Sound	FAIR	Attn	
Oil leakage	FAIR	Attn	にじみあり OIL OOZING
Power	FAIR	Attn	

COOLING SYSTEM

Radiator	FAIR	Attn	
Oil Cooler	FAIR	Attn	

OPERATING SYSTEM

Swing	FAIR	Attn	
Travel	FAIR	Attn	

INTERIOR See Photos. 写真参照

INTERIOR COND.	CLEAN	FAIR	DIRTY
Operator's Seat	FAIR	Attn	
Glasses	FAIR	Attn	
AirCon	A/C	H/C	H only · C only · None

BOOM / ARM / BKT

Boom	FAIR	Attn	
Boom Cylinder	FAIR	Attn	
Arm	FAIR	Attn	
Arm Cylinder	FAIR	Attn	
ATTACHMENT	FAIR	Attn	
BKT Cylinder	FAIR	Attn	

UNDERCARRIAGE : See Photos. 写真参照

RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 3

COMMENT

BKT	STD	SLOPE / NARROW / SKELETON / OTHER ()	
Lever	LONG	WRIST	
Multi	MULTI	2 · NO	
ARM-CRANE	YES	NO	プレート欠損あり PLATE: PARTLY BROKEN
BLADE	YES	NO	
OFFSET	YES	NO	
OFFSET Cylinder	FAIR	Attn	
Piping	YES	NO	Breaker only · Multi

COMMENT

ブームホース背面ヒビあり SOME HOSE AROUND BOOM: CRACKED
CAB内にミラーあり MIRROR: PUTTING IN CAB

RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。