

INSPECTION SHEET 検品書  
OTHER その他

INSPECTION DATE	2026/4/7	CATEGORY	ROAD CUTTER					
MAKE	KOMATSU		MODEL	GC380F-2				
SERIAL	12037		STAMP	GC380F2-12037				
HR METER	16698	HR	Odometer	-	km	YEAR	1996	YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP		<input checked="" type="radio"/> NONE	SHOE		TIRE	14.00-24	

ENGINE	MODEL	S/N
Oil leakage	<input checked="" type="radio"/> FAIR · Attn	Oil <input checked="" type="radio"/> FAIR · Attn
Blow-By	<input checked="" type="radio"/> FAIR · Attn	A LITTLE · MIDDLE · SEVERE
Sound	<input checked="" type="radio"/> FAIR · Attn	Exhaust Color <input checked="" type="radio"/> FAIR · Attn
		EPA YES · <input checked="" type="radio"/> NO

CONDITION	<input checked="" type="radio"/> FAIR · Attn
フィーダーコンベア、フィーダー周りホースひび割れあり FEEDER CONVEYOR & SOME HOSE AROUND FEEDER: CRACKED	

<b>UNDERCARRIAGE : See Photos. 写真参照</b>			
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3	TIRE WEAR	FAIR · <input checked="" type="radio"/> WORN · UNEVEN WEAR
<b>COMMENT</b>			
コンベア调速ダイヤル固着あり CONVEYOR SPEED CONTROL KNOB: STUCK			
シート背もたれ破損あり BACKREST OF SEAT: BROKEN			
パーキング効かない PARKING BRAKE: MALFUNCTION			
油量ランプ点灯あり WARNING LAMP FOR OIL LEVEL: ON			
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2		

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.  
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。