

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2026/6/1	MAKE	KOBELCO	MODEL	SK135SR-2
SERIAL	YY06-18741		STAMP	YY06-18741	
HR METER	7198	HR	YEAR	YR	
CAB/CNP	ROPS CAB / <u>CAB</u> / ROPS CNP / CNP / NONE		SHOE	500G PADS	

ENGINE : MODEL D04FR **S/N** 013793

Oil leakage	<u>FAIR</u>	Attn	
Blow-By	<u>FAIR</u>	Attn	A LITTLE · MIDDLE · SEVERE
Sound	<u>FAIR</u>	Attn	
Oil	<u>FAIR</u>	Attn	
Exhaust Color	<u>FAIR</u>	Attn	
US EPA	YES	<u>NO</u>	

MAIN PUMP

Sound	<u>FAIR</u>	Attn	
Oil leakage	<u>FAIR</u>	Attn	
Power	<u>FAIR</u>	Attn	

COOLING SYSTEM

Radiator	<u>FAIR</u>	Attn	
Oil Cooler	<u>FAIR</u>	Attn	

OPERATING SYSTEM

Swing	<u>FAIR</u>	Attn	
Travel	<u>FAIR</u>	Attn	

INTERIOR See Photos. 写真参照

INTERIOR COND.	CLEAN	<u>FAIR</u>	DIRTY
Operator's Seat	<u>FAIR</u>	Attn	
Glasses	<u>FAIR</u>	Attn	
AirCon	<u>A/C</u>	H/C · H only · C only · None	

BOOM / ARM / BKT

Boom	<u>FAIR</u>	Attn	
Boom Cylinder	<u>FAIR</u>	Attn	
Arm	<u>FAIR</u>	Attn	
Arm Cylinder	<u>FAIR</u>	Attn	
ATTACHMENT	<u>FAIR</u>	Attn	
BKT Cylinder	<u>FAIR</u>	Attn	

UNDERCARRIAGE : See Photos. 写真参照

RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 3

COMMENT

.....
.....
.....
.....
.....

BKT (STD) / SLOPE / NARROW / SKELETON / OTHER ()

Lever LONG · WRIST

Multi MULTI · 2 · NO

ARM-CRANE YES · NO

BLADE YES · NO

OFFSET YES · NO

OFFSET Cylinder FAIR · Attn

Piping YES · NO Breaker only · Multi

COMMENT

ブーム周りホースひび割れあり SOME HOSES AROUND BOOM: CRACKED
コントロールバルブにじみあり CONTROL VALVE: OIL OOZING

.....
.....
.....
.....
.....
.....
.....
.....
.....
.....

RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 2

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。