

INSPECTION SHEET 検品書
ROUGH TERRAIN CRANE ラフタークレーン

INSPECTION DATE	2026/4/3	MAKE	KATO	MODEL	KRM-13H-II
SERIAL No.	PLATE : 5810181	STAMP :		KRC008-0181	
HR METER	25106	HR	Odometer	166649	km
TIRE SIZE	275/80R22.5	YEAR	2010	YR	

ENGINE : MODEL S/N

Oil leakage	FAIR	<input checked="" type="radio"/>	Attn	オイルパンにじみあり OIL PAN: OIL OOZING
Blow-By	FAIR	<input checked="" type="radio"/>	Attn	A LITTLE · MIDDLE · SEVERE
Sound	FAIR	<input checked="" type="radio"/>	Attn	
Oil	FAIR	<input checked="" type="radio"/>	Attn	
Exhaust Color	FAIR	<input checked="" type="radio"/>	Attn	

OPERATION PUMP

Sound	FAIR	<input checked="" type="radio"/>	Attn	
Oil leakage	FAIR	<input checked="" type="radio"/>	Attn	にじみあり OIL OOZING
Power	FAIR	<input checked="" type="radio"/>	Attn	

COOLING SYSTEM

Radiator	FAIR	<input checked="" type="radio"/>	Attn	
Oil Cooler	FAIR	<input checked="" type="radio"/>	Attn	

OPERATING SYSTEM

Computer	OK	<input checked="" type="radio"/>	NG	
Swing	FAIR	<input checked="" type="radio"/>	Attn	
Travel	FAIR	<input checked="" type="radio"/>	Attn	

TRANSMISSION

Transmission	FAIR	<input checked="" type="radio"/>	Attn	
No. OF GEARS	4	GEARS		
4WD	4WD	<input checked="" type="radio"/>	6WD	

INTERIOR See Photos. 写真参照

INTERIOR COND.	CLEAN	<input checked="" type="radio"/>	FAIR	DIRTY
Operator's Seat	FAIR	<input checked="" type="radio"/>	Attn	
Glasses	FAIR	<input checked="" type="radio"/>	Attn	
AirCon	A/C	<input checked="" type="radio"/>	H/C · H only · C only · None	

COMMENT

BOOM

No. of Section	6	SECTIONS	
CRACK/ENFORCEMENT	FAIR	<input checked="" type="radio"/>	Attn
DERRICKING CYL.	FAIR	<input checked="" type="radio"/>	Attn
EXTENSION CYL.	FAIR	<input checked="" type="radio"/>	Attn
JIB	YES	<input checked="" type="radio"/>	NO
JIB TYPE	STD	<input checked="" type="radio"/>	PWR
MAIN & SUB WIRE	YES	<input checked="" type="radio"/>	NO
FREE FALL	YES	<input checked="" type="radio"/>	NO
HOOK	13t, BALL		

UNDERCARRIAGE : See Photos. 写真参照

RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4
TIRE WEAR	FAIR · WORN · UNEVEN WEAR

COMMENT

OUTRIGGERS

OUTRIGGERS	X	<input checked="" type="radio"/>	H	
OUTRIGGERS COND.	FAIR	<input checked="" type="radio"/>	Attn	
Oil leakage (JACK CYL.)	FRONT	L · R	REAR	L · R
Oil leakage (SLIDE CYL.)	FRONT	L · R	REAR	L · R

COMMENT

RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
--	---

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。