

INSPECTION SHEET 検品書
ROUGH TERRAIN CRANE ラフタークレーン

INSPECTION DATE	2026/4/6	MAKE	KATO	MODEL	KR-25H-V5
SERIAL No.	PLATE :	5413153		STAMP :	KR258-3153
HR METER	29374	HR	Odometer	158974	km
TIRE SIZE	385/95R25		YEAR	YR	

ENGINE : MODEL		S/N
Oil leakage	FAIR <input checked="" type="radio"/> Attn	油漏れあり OIL LEAKING
Blow-By	FAIR <input checked="" type="radio"/> Attn	A LITTLE · MIDDLE · SEVERE
Sound	FAIR <input checked="" type="radio"/> Attn	アイドリング不安定 IDLING: UNSTABLE
Oil	FAIR <input type="radio"/> Attn	
Exhaust Color	FAIR <input checked="" type="radio"/> Attn	白煙大 MUCH WHITE FUMES
OPERATION PUMP		
Sound	FAIR <input type="radio"/> Attn	
Oil leakage	FAIR <input type="radio"/> Attn	
Power	FAIR <input type="radio"/> Attn	
COOLING SYSTEM		
Radiator	FAIR <input type="radio"/> Attn	
Oil Cooler	FAIR <input type="radio"/> Attn	
OPERATING SYSTEM		
Computer	OK <input checked="" type="radio"/> NG	
Swing	FAIR <input type="radio"/> Attn	
Travel	FAIR <input type="radio"/> Attn	
TRANSMISSION		
Transmission	FAIR <input type="radio"/> Attn	
No. OF GEARS	4 GEARS	
4WD	4WD <input checked="" type="radio"/> 6WD	
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN · FAIR · DIRTY	
Operator's Seat	FAIR <input type="radio"/> Attn	
Glasses	FAIR <input type="radio"/> Attn	
AirCon	A/C <input checked="" type="radio"/> H/C · H only · C only · None	
COMMENT		

BOOM			
No. of Section	4 SECTIONS		
CRACK/ENFORCEMENT	FAIR <input type="radio"/> Attn		
DERRICKING CYL.	FAIR <input type="radio"/> Attn		
EXTENSION CYL.	FAIR <input type="radio"/> Attn		
JIB	YES <input checked="" type="radio"/> NO		
JIB TYPE	STD <input type="radio"/> PWR <input checked="" type="radio"/>		
MAIN & SUB WIRE	YES <input type="radio"/> NO		
FREE FALL	YES <input type="radio"/> NO		
HOOK	25t, BALL		
UNDERCARRIAGE : See Photos. 写真参照			
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			2
TIRE WEAR	FAIR <input checked="" type="radio"/> WORN · UNEVEN WEAR		
COMMENT			
OUTRIGGERS			
OUTRIGGERS	X <input type="radio"/> H <input checked="" type="radio"/>		
OUTRIGGERS COND.	FAIR <input type="radio"/> Attn		
Oil leakage (JACK CYL.)	FRONT	L · R	REAR L · R
Oil leakage (SLIDE CYL.)	FRONT	L · R	REAR L · R
COMMENT			
穴あり HOLES			
過巻コード切れあり OVERWINDING PREVENTION CORD: CUT			
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			1

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。