

INSPECTION SHEET 検品書
ROUGH TERRAIN CRANE ラフタークレーン

INSPECTION DATE	2026/4/7	MAKE	KOMATSU	MODEL	LW80M-1
SERIAL No.	PLATE :	10311	STAMP :	L002-10311	
HR METER	7122	HR	Odometer	2074	km
TIRE SIZE	11R22.5 16PR		YEAR	YR	

ENGINE : MODEL S/N

Oil leakage	FAIR <input checked="" type="radio"/> Attn	E/Gヘッドにじみあり CYLINDER HEAD: OIL OozING
Blow-By	FAIR <input checked="" type="radio"/> Attn	A LITTLE <input checked="" type="radio"/> MIDDLE <input type="radio"/> SEVERE
Sound	FAIR <input type="radio"/> Attn	
Oil	FAIR <input type="radio"/> Attn	
Exhaust Color	FAIR <input type="radio"/> Attn	

OPERATION PUMP

Sound	FAIR <input type="radio"/> Attn	
Oil leakage	FAIR <input type="radio"/> Attn	
Power	FAIR <input type="radio"/> Attn	

COOLING SYSTEM

Radiator	FAIR <input type="radio"/> Attn	
Oil Cooler	FAIR <input type="radio"/> Attn	

OPERATING SYSTEM

Computer	OK <input checked="" type="radio"/> NG	
Swing	FAIR <input type="radio"/> Attn	
Travel	FAIR <input type="radio"/> Attn	

TRANSMISSION

Transmission	FAIR <input type="radio"/> Attn	
No. OF GEARS	3 GEARS	
4WD	4WD <input type="radio"/> 6WD	

INTERIOR See Photos. 写真参照

INTERIOR COND.	CLEAN <input type="radio"/> FAIR <input checked="" type="radio"/> DIRTY	
Operator's Seat	FAIR <input type="radio"/> Attn	穴、破れあり CUTS
Glasses	FAIR <input type="radio"/> Attn	
AirCon	A/C <input type="radio"/> H/C <input checked="" type="radio"/> H only <input type="radio"/> C only <input type="radio"/> None	

COMMENT

BOOM

No. of Section	6	SECTIONS	
CRACK/ENFORCEMENT	FAIR <input type="radio"/> Attn		
DERRICKING CYL.	FAIR <input type="radio"/> Attn		
EXTENSION CYL.	FAIR <input type="radio"/> Attn	ホース油漏れあり HOSE: OIL LEAKING	
JIB	YES <input type="radio"/> NO <input checked="" type="radio"/>		
JIB TYPE	STD <input type="radio"/> PWR		
MAIN & SUB WIRE	YES <input type="radio"/> NO		
FREE FALL	YES <input type="radio"/> NO		
HOOK	4.9t, BALL		

UNDERCARRIAGE : See Photos. 写真参照

RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	1
TIRE WEAR	FAIR <input checked="" type="radio"/> WORN <input type="radio"/> UNEVEN WEAR

COMMENT

右フハブ油漏れあり FRONT RIGHT HUB: OIL LEAKING
リアステアシリンダーホース油漏れあり REAR STEERING CYLINDER HOSE: OIL LEAKING

OUTRIGGERS

OUTRIGGERS	X <input type="radio"/> H <input checked="" type="radio"/>		
OUTRIGGERS COND.	FAIR <input type="radio"/> Attn		
Oil leakage (JACK CYL.)	FRONT	L <input type="radio"/> R <input type="radio"/>	REAR L <input type="radio"/> R <input type="radio"/>
Oil leakage (SLIDE CYL.)	FRONT	L <input type="radio"/> R <input type="radio"/>	REAR L <input type="radio"/> R <input type="radio"/>

COMMENT

過巻不良 OVERWINDING PREVENTION: MALFUNCTION
ロータリージョイント油漏れあり ROTARY JOINT: OIL LEAKING

RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	1
--	---

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。