

INSPECTION SHEET 検品書  
ROUGH TERRAIN CRANE ラフタークレーン

INSPECTION DATE	2026/4/6	MAKE	TADANO	MODEL	TR-250M-5
SERIAL No.	PLATE : FB0334	STAMP : TR253-1938			
HR METER	1186 + ?	HR	Odometer	4842 + 52706	km
TIRE SIZE	17.5R29	YEAR	YR		

<b>ENGINE : MODEL</b>		<b>S/N</b>
Oil leakage	<input type="radio"/> FAIR · Attn	
Blow-By	<input type="radio"/> FAIR · Attn	A LITTLE · MIDDLE · SEVERE
Sound	<input type="radio"/> FAIR · Attn	
Oil	<input type="radio"/> FAIR · Attn	
Exhaust Color	<input type="radio"/> FAIR · Attn	
<b>OPERATION PUMP</b>		
Sound	<input type="radio"/> FAIR · Attn	
Oil leakage	<input type="radio"/> FAIR · Attn	
Power	<input type="radio"/> FAIR · Attn	
<b>COOLING SYSTEM</b>		
Radiator	<input type="radio"/> FAIR · Attn	
Oil Cooler	<input type="radio"/> FAIR · Attn	
<b>OPERATING SYSTEM</b>		
Computer	OK <input type="radio"/> NG *1	
Swing	<input type="radio"/> FAIR · Attn	
Travel	<input type="radio"/> FAIR · Attn	
<b>TRANSMISSION</b>		
Transmission	<input type="radio"/> FAIR · Attn	
No. OF GEARS	3 GEARS	
4WD	<input type="radio"/> 4WD · 6WD	
<b>INTERIOR See Photos. 写真参照</b>		
INTERIOR COND.	CLEAN · <input type="radio"/> FAIR · DIRTY	
Operator's Seat	<input type="radio"/> FAIR · Attn	
Glasses	<input type="radio"/> FAIR · Attn	
AirCon	<input type="radio"/> A/C · H/C · H only · C only · None	
<b>COMMENT</b>		
メーター交換歴あり (HRメーターは交換時期不明)		
METERS: REPLACED (HR METER REPLACEMENT TIME: UNKNOWN)		
穴あり BODY: HOLES		

<b>BOOM</b>	
No. of Section	4 SECTIONS
CRACK/ENFORCEMENT	<input type="radio"/> FAIR · Attn
DERRICKING CYL.	<input type="radio"/> FAIR · <input checked="" type="radio"/> Attn *2
EXTENSION CYL.	<input type="radio"/> FAIR · Attn
JIB	<input checked="" type="radio"/> YES · NO
JIB TYPE	STD · <input checked="" type="radio"/> PWR
MAIN & SUB WIRE	<input checked="" type="radio"/> YES · NO
FREE FALL	<input checked="" type="radio"/> YES · NO
HOOK	25t, BALL
<b>UNDERCARRIAGE : See Photos. 写真参照</b>	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	1
TIRE WEAR	<input checked="" type="radio"/> FAIR · <input type="radio"/> WORN · <input type="radio"/> UNEVEN WEAR
<b>COMMENT</b>	
リアステロック不良 REAR STEERING LOCK: MALFUNCTION	
ブーム伸縮未確認 BOOM TELESCOPING OPERATION: NOT CHECKED	
<b>OUTRIGGERS</b>	
OUTRIGGERS	<input checked="" type="radio"/> X · H *3
OUTRIGGERS COND.	<input type="radio"/> FAIR · Attn
Oil leakage (JACK CYL.)	FRONT L · R REAR L · R
Oil leakage (SLIDE CYL.)	FRONT L · R REAR L · R
<b>COMMENT</b>	
*1 CPUエラーあり (検品時確認)、モニター表示不良	
*1 CPU ERROR DISPLAY (JUST CHECKED AT THE INSPECTION TIME), MONITOR: MALFUNCTION TO DISPLAY	
*2 自然降下大 (起伏後レバーを放すとすぐに落ちてくる)	
*2 SEVERE HYDRAULIC DRIFT (IMMEDIATELY GOING DOWN WHEN RELEASING THE OPERATION LEVER)	
*3 下で操作 NEED TO OPERATE FROM OUTSIDE	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	1

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.  
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。