

INSPECTION SHEET 検品書
ROUGH TERRAIN CRANE ラフタークレーン

INSPECTION DATE	2026/4/6	MAKE	KOMATSU	MODEL	LW250-5
SERIAL No.	PLATE : 50337	STAMP :		L003-50337	
HR METER	788	HR	Odometer	584	km
TIRE SIZE	385/95R25	YEAR	YR		

ENGINE : MODEL		S/N
Oil leakage	<input type="radio"/> FAIR · <input type="radio"/> Attn	
Blow-By	<input type="radio"/> FAIR · <input type="radio"/> Attn	A LITTLE · MIDDLE · SEVERE
Sound	<input type="radio"/> FAIR · <input type="radio"/> Attn	
Oil	<input type="radio"/> FAIR · <input type="radio"/> Attn	
Exhaust Color	<input type="radio"/> FAIR · <input type="radio"/> Attn	
OPERATION PUMP		
Sound	<input type="radio"/> FAIR · <input type="radio"/> Attn	
Oil leakage	<input type="radio"/> FAIR · <input checked="" type="radio"/> Attn	にじみあり OIL OOZING
Power	<input type="radio"/> FAIR · <input type="radio"/> Attn	
COOLING SYSTEM		
Radiator	<input type="radio"/> FAIR · <input type="radio"/> Attn	
Oil Cooler	<input type="radio"/> FAIR · <input type="radio"/> Attn	
OPERATING SYSTEM		
Computer	<input checked="" type="radio"/> OK · <input type="radio"/> NG	
Swing	<input type="radio"/> FAIR · <input type="radio"/> Attn	
Travel	<input type="radio"/> FAIR · <input type="radio"/> Attn	
TRANSMISSION		
Transmission	<input type="radio"/> FAIR · <input type="radio"/> Attn	
No. OF GEARS	3 GEARS	
4WD	<input checked="" type="radio"/> 4WD · <input type="radio"/> 6WD	
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN · <input checked="" type="radio"/> FAIR · <input type="radio"/> DIRTY	
Operator's Seat	<input type="radio"/> FAIR · <input type="radio"/> Attn	破れあり CUTS
Glasses	<input type="radio"/> FAIR · <input type="radio"/> Attn	
AirCon	<input checked="" type="radio"/> A/C · <input type="radio"/> H/C · <input type="radio"/> H only · <input type="radio"/> C only · <input type="radio"/> None	
COMMENT		

BOOM			
No. of Section	5 SECTIONS		
CRACK/ENFORCEMENT	<input type="radio"/> FAIR · <input type="radio"/> Attn		
DERRICKING CYL.	<input type="radio"/> FAIR · <input checked="" type="radio"/> Attn	にじみあり OIL OOZING	
EXTENSION CYL.	<input type="radio"/> FAIR · <input type="radio"/> Attn		
JIB	<input checked="" type="radio"/> YES · <input type="radio"/> NO		
JIB TYPE	<input type="radio"/> STD · <input type="radio"/> PWR		
MAIN & SUB WIRE	<input checked="" type="radio"/> YES · <input type="radio"/> NO		
FREE FALL	<input checked="" type="radio"/> YES · <input type="radio"/> NO		
HOOK	26t, BALL		
UNDERCARRIAGE : See Photos. 写真参照			
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			1
TIRE WEAR		<input checked="" type="radio"/> FAIR · <input type="radio"/> WORN · <input type="radio"/> UNEVEN WEAR	
COMMENT			
穴あり MUCH HOLES			
OUTRIGGERS			
OUTRIGGERS	<input checked="" type="radio"/> X · <input type="radio"/> H		
OUTRIGGERS COND.	<input type="radio"/> FAIR · <input type="radio"/> Attn		
Oil leakage (JACK CYL.)	FRONT	L · R	REAR L · R
Oil leakage (SLIDE CYL.)	FRONT	L · R	REAR L · R
COMMENT			
異音あり(プロペラシャフト周り?) AROUND PROPELLER SHAFT?: NOISES			
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。