

INSPECTION SHEET 検品書
ROUGH TERRAIN CRANE ラフタークレーン

INSPECTION DATE	2026/4/3	MAKE	TADANO	MODEL	GR-160N-3
SERIAL No.	PLATE :	526663	STAMP :	T009-0126	
HR METER	23946	HR	Odometer	145405	km
TIRE SIZE	325/95R24		YEAR	YR	

ENGINE : MODEL	S/N
Oil leakage	<input type="radio"/> FAIR · <input type="radio"/> Attn
Blow-By	<input type="radio"/> FAIR · <input type="radio"/> Attn A LITTLE · MIDDLE · SEVERE
Sound	<input type="radio"/> FAIR · <input type="radio"/> Attn
Oil	<input type="radio"/> FAIR · <input type="radio"/> Attn
Exhaust Color	<input type="radio"/> FAIR · <input type="radio"/> Attn
OPERATION PUMP	
Sound	<input type="radio"/> FAIR · <input type="radio"/> Attn
Oil leakage	<input type="radio"/> FAIR · <input checked="" type="radio"/> Attn にじみあり OIL OOZING
Power	<input type="radio"/> FAIR · <input type="radio"/> Attn
COOLING SYSTEM	
Radiator	<input type="radio"/> FAIR · <input type="radio"/> Attn
Oil Cooler	<input type="radio"/> FAIR · <input type="radio"/> Attn
OPERATING SYSTEM	
Computer	<input checked="" type="radio"/> OK · <input type="radio"/> NG
Swing	<input type="radio"/> FAIR · <input type="radio"/> Attn
Travel	<input type="radio"/> FAIR · <input type="radio"/> Attn
TRANSMISSION	
Transmission	<input type="radio"/> FAIR · <input type="radio"/> Attn
No. OF GEARS	3 GEARS
4WD	<input checked="" type="radio"/> 4WD · <input type="radio"/> 6WD
INTERIOR See Photos. 写真参照	
INTERIOR COND.	<input checked="" type="radio"/> CLEAN · <input type="radio"/> FAIR · <input type="radio"/> DIRTY
Operator's Seat	<input type="radio"/> FAIR · <input checked="" type="radio"/> Attn 破れあり HUGE CUTS
Glasses	<input type="radio"/> FAIR · <input type="radio"/> Attn
AirCon	<input checked="" type="radio"/> A/C · <input type="radio"/> H/C · <input type="radio"/> H only · <input type="radio"/> C only · <input type="radio"/> None
COMMENT	

BOOM	
No. of Section	6 SECTIONS
CRACK/ENFORCEMENT	<input type="radio"/> FAIR · <input type="radio"/> Attn
DERRICKING CYL.	<input type="radio"/> FAIR · <input type="radio"/> Attn
EXTENSION CYL.	<input type="radio"/> FAIR · <input checked="" type="radio"/> Attn ホースにじみあり HOSE: OIL OOZING
JIB	<input checked="" type="radio"/> YES · <input type="radio"/> NO
JIB TYPE	<input checked="" type="radio"/> STD · <input type="radio"/> PWR
MAIN & SUB WIRE	<input checked="" type="radio"/> YES · <input type="radio"/> NO
FREE FALL	<input type="radio"/> YES · <input checked="" type="radio"/> NO
HOOK	16t, BALL
UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4
TIRE WEAR	<input type="radio"/> FAIR · <input checked="" type="radio"/> WORN · <input type="radio"/> UNEVEN WEAR
COMMENT	
OUTRIGGERS	
OUTRIGGERS	<input checked="" type="radio"/> X · <input type="radio"/> H
OUTRIGGERS COND.	<input type="radio"/> FAIR · <input type="radio"/> Attn
Oil leakage (JACK CYL.)	FRONT L · R REAR L · R
Oil leakage (SLIDE CYL.)	FRONT L · R REAR L · R
COMMENT	
オイルエレメントホースにじみあり OIL FILTER HOSE: OIL OOZING	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。