

INSPECTION SHEET 検品書
ROUGH TERRAIN CRANE ラフタークレーン

INSPECTION DATE	2026/4/7	MAKE	TADANO	MODEL	GR-120N-1
SERIAL No.	PLATE : FD1209	STAMP :		TR120-1191	
HR METER	16070	HR	Odometer	157182	km
TIRE SIZE	275/80R22.5		YEAR	YR	

ENGINE : MODEL		S/N
Oil leakage	FAIR <input checked="" type="radio"/> Attn *1	
Blow-By	FAIR <input checked="" type="radio"/> Attn	A LITTLE · MIDDLE · SEVERE
Sound	FAIR <input checked="" type="radio"/> Attn	
Oil	FAIR <input checked="" type="radio"/> Attn	
Exhaust Color	FAIR <input checked="" type="radio"/> Attn	
OPERATION PUMP		
Sound	FAIR <input checked="" type="radio"/> Attn	
Oil leakage	FAIR <input checked="" type="radio"/> Attn	
Power	FAIR <input checked="" type="radio"/> Attn	
COOLING SYSTEM		
Radiator	FAIR <input checked="" type="radio"/> Attn	
Oil Cooler	FAIR <input checked="" type="radio"/> Attn	
OPERATING SYSTEM		
Computer	OK <input checked="" type="radio"/> NG	
Swing	FAIR <input checked="" type="radio"/> Attn	
Travel	FAIR <input checked="" type="radio"/> Attn	
TRANSMISSION		
Transmission	FAIR <input checked="" type="radio"/> Attn	
No. OF GEARS	3 GEARS	
4WD	4WD <input checked="" type="radio"/> 6WD	
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN <input checked="" type="radio"/> FAIR · DIRTY	
Operator's Seat	FAIR <input checked="" type="radio"/> Attn	
Glasses	FAIR <input checked="" type="radio"/> Attn	
AirCon	A/C <input checked="" type="radio"/> H/C · H only · C only · None	
COMMENT		

BOOM	
No. of Section	6 SECTIONS
CRACK/ENFORCEMENT	FAIR <input checked="" type="radio"/> Attn
DERRICKING CYL.	FAIR <input checked="" type="radio"/> Attn
EXTENSION CYL.	FAIR <input checked="" type="radio"/> Attn
JIB	YES <input checked="" type="radio"/> NO
JIB TYPE	STD · PWR <input checked="" type="radio"/>
MAIN & SUB WIRE	YES <input checked="" type="radio"/> NO
FREE FALL	YES · NO <input checked="" type="radio"/>
HOOK	12t, BALL
UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4
TIRE WEAR	FAIR <input checked="" type="radio"/> WORN · UNEVEN WEAR
COMMENT	
右Rタイヤサイド亀裂あり REAR RIGHT TIRE SIDEWALL: CRACKED 前後ステアリングシリンダー油漏れあり STEERING CYLINDERS: OIL LEAKING	
OUTRIGGERS	
OUTRIGGERS	X · H <input checked="" type="radio"/>
OUTRIGGERS COND.	FAIR <input checked="" type="radio"/> Attn
Oil leakage (JACK CYL.)	FRONT L <input checked="" type="radio"/> R REAR L · R
Oil leakage (SLIDE CYL.)	FRONT L · R REAR L · R
COMMENT	
*1 E/Gヘッドにじみ、オイルパン油漏れあり *1 CYLINDER HEAD: OIL OOZING, OIL PAN: OIL LEAKING	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
4	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。