# INSPECTION SHEET 検品書
## WHEEL LOADER タイヤショベル

| | | | | | |
|---|---|---|---|---|---|
| INSPECTION DATE | 2026/3/16 | MAKE | CAT | MODEL | 950MZ |
| SERIAL | CAT0950MTHE810309 | | STAMP | CAT0950MTHE810309 | |
| HR METER | 11013 / 11042 HR | Odometer | 49756 km | YEAR | YR |
| CAB/CNP | ROPS CAB / CAB / ROPS CNP / CNP / NONE | | TIRE SIZE | 23.5-25 | |

| ENGINE : MODEL C7.1 S/N D8T26310 | | |
|---|---|---|
| Oil leakage | FAIR・Attn | |
| Blow-By | FAIR・Attn | A LITTLE・MIDDLE・SEVERE |
| Sound | FAIR・Attn | |
| Oil | FAIR・Attn | |
| Exhaust Color | FAIR・Attn | |
| US EPA | YES・NO | |
| **OPERATION PUMP** | | |
| Sound | FAIR・Attn | |
| Oil leakage | FAIR・Attn | |
| Power | FAIR・Attn | |
| **COOLING SYSTEM** | | |
| Radiator | FAIR・Attn | |
| Oil Cooler | FAIR・Attn | |
| **TRANSMISSION & TRAVEL** | | |
| T/M TYPE | PS・DD | |
| Transmission | FAIR・Attn | |
| Travel | FAIR・Attn | |
| FOOT BRAKE | FAIR・Attn | |
| PARKING BRAKE | FAIR・Attn | |
| **INTERIOR** See Photos. 写真参照 | | |
| INTERIOR COND. | CLEAN・FAIR・DIRTY | |
| Operator's Seat | FAIR・Attn | |
| Glasses | FAIR・Attn | |
| AirCon | A/C・H/C・H only・C only・None | |
| **FRONT & CYLINDERS** | | |
| Arm | FAIR・Attn | |
| Bell crank | FAIR・Attn | |
| Bucket | FAIR・Attn | |
| Articulate | FAIR・Attn | |

| UNDERCARRIAGE : See Photos. 写真参照 | | | |
|---|---|---|---|
| RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) | | | 3 |
| TIRE WEAR | FAIR・WORN・UNEVEN WEAR | | |
| **COMMENT** | | | |
| STEERING TYPE | WHEEL STEERING / COMMAND STEERING / LEVER STEERING | | |
| RIDE CONTROL | YES・NO | | |
| **ATTACHMENTS** | | | |
| STD BKT | YES・OTHER | | |
| BLADE | YES・NO | Piping for Tilt | YES・NO |
| **COMMENT** | | | |
| RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) | | | 3 |

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。